



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14159143 - 2022 Volvo A25G Articulated Dump Truck



Item Details:

- Features: Air Conditioner, Rear View Camera, 2021 US EPA Label, Requires Diesel Exhaust Fluid, Tailgate, Steel Body Liner
- Meter Reading: 2,311 Miles
- Serial #: VCE0A25GE00752372
- Inspection Completed: 4/14/25

Shipping Details:

- Location Georgia (Atlanta area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Already onsite

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★★☆	Performs within the tolerances expected for age and type of item
★★★☆☆	Although performing, shows indication of needing repair or replacement
★★☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Chassis #22		

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	VCE0A25GE00752372	
Paint	Damage	

Body Panels	Left side of hood damaged	
Mud Flaps	No visible damage or missing components	
Steps	No visible damage or missing components.	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
Articulated Dump* # 1		
Articulated Dump* # 2		

Articulated Dump* # 3		
Articulated Dump* # 4		

Safety

Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station

Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	Cab door cracked	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter / Odometer	2311 mi	
Air Conditioner	Inoperable, Fans work but no cold air	



Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Articulated Dump* # 1		
Articulated Dump* # 2		
Articulated Dump* # 3		
Articulated Dump* # 4		

Engine		
Item	Assessment	Photo
Engine	2021 US EPA Label, Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Compressor will not engage	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		

Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	After jump starting, the engine ran.	
Engine #1		
Engine #2		
Engine #3		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Steer Axle	★★☆☆	
Center Drive Axle	★★☆☆	
Rear Drive Axle	★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		

Hydraulics

See photos for condition

Item	Assessment	Photo
Pumps (Hydraulics)	★★★☆☆	
Valves	★★★☆☆	
Hydraulic Tank	★★★☆☆	
Hoses		
Cylinders	★★★☆☆	
Steering Cylinders	★★★☆☆	
Limited Function Check	The hydraulic system was operational.	

Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		



Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Oscillating Hitch	★★★★☆	
Frame Condition	★★★★☆	
Suspension Cylinders	★★★★☆	
Suspension Pivot Points	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder/Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	

Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Left Front Tire	★★★★☆ Bridgestone VLTS 23.5R25 39/32" Tread Depth	
Left Middle Tire	★★★★☆ Bridgestone VLTS 23.5R25 40/32" Tread Depth	
Left Rear Tire	★★★★☆ Bridgestone VLTS 23.5R25 39/32" Tread Depth	
Right Rear Tire	★★★★☆ Bridgestone VLTS 23.5R25 39/32" Tread Depth	
Right Middle Tire	★★★★☆ Bridgestone VLTS 23.5R25 39/32" Tread Depth	
Right Front Tire	★★★★☆ Bridgestone VLTS 23.5R25 39/32" Tread Depth	

Wheel Condition	No visible damage or missing components	
Bed Body	★★★★☆	
Bed Liner	★★★★☆	
Tail Gate	★★★★☆	
Bed Pads	★★★★☆	
Hinge Points	★★★★☆	
Limited Function Check	The main chassis components were operational in a limited check.	

Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		

Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		
Chassis #13		
Chassis #14		

Chassis #15		
Chassis #16		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved