



DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
04/08/2021	HC713764	

INSPECTOR: 5932  
INSPECTION ID  
139139

Year	2017	Make	PREVOST
Model	H3-45	VIN	2PCH33490HC713764

### SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	BLUE

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13
Eng Serial:	0131167387
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	149"
Overall Width:	102"

Engine Options B	
Odometer:	318624
Hub odometer:	NA
ECU HP:	500
ECU Miles:	318638
Eng Hours:	NA

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	229

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	315
Rear Ratio:	2.50
F Axle (lbs):	16,500
R Axle (lbs):	14,000
GVWR (lbs):	53,00
Suspension:	AIR RIDE
Tag Axle Capacity:	22,500
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	5TH GEN 3000/4000
Trans Speed:	6

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additional comments:	
NA	



DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

INSP DATE | VIN (LAST 8) | PO NUMBER  
04/08/2021 | HC713764 |

INSPECTOR: 5932  
INSPECTION ID  
139139

### Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	NO
DRUM:	YES
Brake Plates:	FRONT N / REAR N

### Tires [Front]











Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

### Brakes

Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

### Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		6 / 32nd LUG / R1	4 / 32nd LUG / R1
RIGHT	11 / 32nd HIGHWAY / V 	 	 
FRONT		6 / 32nd LUG / R1	/ 32nd /
LEFT	 10 / 32nd HIGHWAY / V	8 / 32nd LUG / R1  	/ 32nd /  
		6 / 32nd LUG / R1	6 / 32nd LUG / R1

### Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP  
CL = CRACKED LINING  
LS = LEAKING SEAL(S)

### Tire Legend

C = CUT D = DRY ROT F = FLAT  
M = MISMATCHED TIRES/CASING  
MA = MISMATCHED AXLES (FRONT vs.  
REAR)  
V = VIRGIN W = IRREGULAR WEAR  
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

### Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.  
Customer Service 770-257-0107

BUS

INSPECTOR: 5932  
INSPECTION ID  
139139

INSP DATE | VIN (LAST 8) | PO NUMBER  
04/08/2021 | HC713764 |

CONDITION REPORT

Engine Compartment Area		COMMENTS
Operational Test		COMMENTS
X	Engine Warning System	ACTIVE CODES
In Cab Inspection		COMMENTS
Outside Inspection		COMMENTS
X	Paint Condition & Physical Damage	BODY DAMAGE
Under Vehicle Inspection		COMMENTS
Tires/Wheels/Brakes		COMMENTS
X	Tires/Wheels	6 TIRES

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

## BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
04/08/2021	HC713764	

INSPECTOR: 5932  
INSPECTION ID  
139139

### RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Engine Warning System	X   ACTIVE CODES
Paint Condition & Physical Damage	X   BODY DAMAGE
Tires/Wheels	X   6 TIRES
FRONT BUMPER	DAMAGE
FRONT PANEL	REFINISH
ENTRY DOOR	REFINISH
ENTRY DOOR LOWER MOLDING	DAMAGE
RIGHT SIDE ENGINE DOOR MOLDING	DAMAGE
LEFT SIDE PANEL	DECAL ADHESIVE DAMAGE REFINISH
RIGHT SIDE # 6 WINDOW	UPPER MOLDING MISSING
REAR BUMPER	DAMAGE

#### COMMENTS:

THE BUS WAS INSPECTED AT PREVOST IN MIRA LOMA. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WERE ACTIVE ENGINES CODES, BODY DAMAGE AND BAD TIRES. THERE WAS ONE TABLE WITH A USB PORT.



DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

INSP DATE | VIN (LAST 8) | PO NUMBER  
04/08/2021 | HC713764 |

INSPECTOR: 5932  
INSPECTION ID  
139139



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT  
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO  
BACK





DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

INSP DATE | VIN (LAST 8) | PO NUMBER  
04/08/2021 | HC713764


INSPECTOR: 5932  
INSPECTION ID  
139139



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT



FLOOR OF BUS, BACK TO FRONT



INSIDE RESTROOM #1



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT  
RIGHT SIDE



ENGINE COMPARTMENT LEFT  
SIDE



INSIDE STORAGE  
COMPARTMENTS



J PRO



USB PORT



ADDITIONAL 1



ADDITIONAL 2



DEKRA Services Inc.  
Customer Service 770-257-0107

## BUS

INSP DATE | VIN (LAST 8) | PO NUMBER  
04/08/2021 | HC713764 |

INSPECTOR: 5932  
INSPECTION ID  
139139



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13