



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

INSPECTOR: 5761  
 INSPECTION ID  
 132955

INSP DATE | VIN (LAST 8) | PO NUMBER  
 12/03/2020 | GW067371 |

Year: 2016 Make: MCI  
 Model: J4500 VIN: 2MG3JM8A8GW067371

SPECIFICATION WORKSHEET

<b>Interior Options</b>	
Interior Color:	GREY

<b>Steering Options</b>	
Power Steering?:	Yes

<b>Engine Options A</b>	
Eng Make:	CUMMINS
Eng Model:	X12
Eng Serial:	N/A
Eng HP:	410
Cruise:	Yes
Clean air idle:	Yes

<b>Overall Condition</b>	
Overall Length:	45.58
Overall Height:	140.75
Overall Width:	102

<b>Engine Options B</b>	
Odometer:	181763
Hub odometer:	
ECU HP:	
ECU Miles:	
Eng Hours:	N/A

<b>Miscellaneous</b>	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	2
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	No
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	
Any extra options or features not listed on front page and any additional comments:	

<b>Engine Options C</b>	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	183

<b>Exterior Options A</b>	
Air Horns:	SINGLE
Mirrors:	DUAL POWER
Exterior Color:	BLACK/WHITE

<b>Axle / Susp Options</b>	
WheelBase (In):	315
Rear Ratio:	
F Axle (lbs):	9500
R Axle (lbs):	23000
GVWR (lbs):	54000
Suspension:	AIR RIDE
Tag Axle Capacity:	16500
Rear Axle Model:	
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

<b>Transmission Options</b>	
Trans Make:	ALLISON
Trans Model:	GEN V
Trans Speed:	10



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

INSPECTOR: 5761  
 INSPECTION ID  
 132955











INSP DATE | VIN (LAST 8) | PO NUMBER  
 12/03/2020 | GW067371 |

Brakes Options	
ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes			
Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Front]	
Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]	
Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		7 / 32nd HIGHWAY / V	7 / 32nd HIGHWAY / V
RIGHT	9 / 32nd HIGHWAY / V 	 	 
FRONT		/ 32nd HIGHWAY / V	8 / 32nd HIGHWAY / V
		/ 32nd HIGHWAY / V	7 / 32nd HIGHWAY / V
LEFT	 9 / 32nd HIGHWAY / V	 	 
		7 / 32nd HIGHWAY / V	7 / 32nd HIGHWAY / V

Brake Legend
BD = DRUM HAS MORE THAN 1/16 INCH LIP CL = CRACKED LINING LS = LEAKING SEAL(S)
Tire Legend
C = CUT D = DRY ROT F = FLAT M = MISMATCHED TIRES/CASING MA = MISMATCHED AXLES (FRONT vs. REAR) V = VIRGIN W = IRREGULAR WEAR R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES
Tread Legend
H = HIGHWAY L = LUG



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

INSPECTOR: 5761  
 INSPECTION ID  
 132955

INSP DATE | VIN (LAST 8) | PO NUMBER  
 12/03/2020 | GW067371 |

CONDITION REPORT

Engine Compartment Area		COMMENTS
OK	Fan Assembly, Shroud & Radiator	
OK	Hose Condition	
OK	Record Coolant Protection Level	
OK	Oil in Cooling System	
OK	Coolant DCA Level	
OK	Coolant Level	
OK	Power/Manual Steering Fluid Level	
OK	Clutch Master Cylinder Fluid Level	
OK	Brake Fluid Level	
OK	Engine Oil Level	
OK	Oil, Coolant and Other Fluid Leaks	
OK	Belt, Alignment, Condition & Adjustment	
OK	Belt & Engine Driven Components	
OK	Exhaust & Intake Systems	
OK	Visible Inspection of Starter	
	Other	
Operational Test		COMMENTS
OK	Batteries - Capable of Starting Engine	
OK	Starter Condition	
OK	Steering Free Play	
OK	Clutch & Clutch Brake	
OK	Transmission Shifts	
OK	Brakes & Parking Brakes	
OK	Throttle	
OK	Engine Brake	
OK	Air Pressure Build Up	
OK	Governed Air Pressure (psi)	
OK	Low Air Warning	
OK	Gauges	
OK	Engine Warning System	
OK	Seat Belts	
OK	HVAC System	
OK	Record A/C Temperature	
OK	Windshield Wipers & Washers	
OK	Horns	
OK	Door Locks & Latches	
OK	Window Operation	
	Other	
In Cab Inspection		COMMENTS
OK	Windshield, Door & Any Other Glass	
OK	Interior Condition/ Seats, Panels, Etc.	
OK	DOT Required Safety Equipment	
	Other	
Outside Inspection		COMMENTS
X	Paint Condition & Physical Damage	REAR PANEL damaged
OK	Mirrors	
OK	Lights and Reflectors	
OK	Fuel Tank Mounting & Condition	
OK	Batteries & Battery Box	
OK	Intake & Exhaust Mounting & Condition	
	Other	
Under Vehicle Inspection		COMMENTS
OK	Kingpins/Steering Components	
OK	Engine/Transmission Mounts	
OK	Frame, Crossmembers, Fasteners	
OK	Cab Mounts	
OK	Driveshafts, U-joints, Yokes	
OK	Hydraulic Brake Lines & Components	
OK	Brake Hoses for Chafing & Cracking	
OK	Air Brake Components	
OK	Transmission & Differential Fluid Levels	
OK	Transmission & Differential Leaks	
OK	Air Leaks	
OK	Suspension Condition	
	Other	
Tires/Wheels/Brakes		COMMENTS
X	Tires/Wheels	8 tires under 10/32
OK	Brakes	

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

**INSPECTOR: 5761**  
**INSPECTION ID**  
**132955**

<b>INSP DATE</b>	<b>VIN (LAST 8)</b>	<b>PO NUMBER</b>
12/03/2020	GW067371	

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Paint Condition & Physical Damage	X   REAR PANEL damaged
Tires/Wheels	X   8 tires under 10/32

**COMMENTS:**  
UNIT OBSERVED IN GOOD OVERALL USED CONDITION. NO INTERIOR DAMAGE NOTED. TIRES ARE WORN BUT STILL USABLE AT THIS TIME. . D ENGINE COMPARTMENT LOOKS GOOD, HOWEVER NO ENGINE LABEL VISIBLE. NO APPARENT LEAKS NOTED. ALL FLUID LEVELS ARE GOOD. UNIT STARTS AND OPERATES PROPERLY. MINOR DAMAGE HAS BEEN REPAIRED TO REAR PANEL BUT NEEDS REFINISH, NOTED. NO OTHER DAMAGE OF NOTE.



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

**INSPECTOR: 5761**  
**INSPECTION ID**  
**132955**

**INSP DATE** | **VIN (LAST 8)** | **PO NUMBER**  
 12/03/2020 | GW067371 |



VIN



DASH W/ STEERING WHEEL



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR LEFT CORNER



LEFT REAR TIRES




ENTRY WAY STEPS AT FRONT DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO BACK



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT



INSIDE RESTROOM #1



DEKRA Services Inc.  
Customer Service 770-257-0107

**BUS**

INSPECTOR: 5761  
INSPECTION ID  
132955

INSP DATE | VIN (LAST 8) | PO NUMBER  
12/03/2020 | GW067371



INSIDE RESTROOM #2



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE COMPARTMENT  
RIGHT SIDE



ENGINE COMPARTMENT LEFT  
SIDE



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10




**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**BUS**

INSP DATE	VIN (LAST 8)	PO NUMBER
12/03/2020	GW067371	

INSPECTOR: 5761  
INSPECTION ID  
132955



ADDITIONAL 11



ADDITIONAL 12