



Buy this item and view more at www.truckplanet.com or call 800-211-3983

Item #15092790 - 2019 Hyundai HD 160D-9 36000 lb Forklift



Item Details:

- Features: 2 Stage Mast, Full Free Lift, 197 in Max Lift Height, 170 in Lowered Mast Height, 52 in Forks, Side Shift, Solid Pneumatic Tires
- Meter Reading: 0 Hours
- Serial # : HHKHFT23KJ0000197
- Inspection Completed: 4/15/26





Shipping Details:

- Location Washington (Lewis County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected







General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		






<p>Serial Number / VIN</p>	<p>HHKHFT23KJ0000197</p>	
<p>Paint</p>	<p>Damage</p>	
<p>Body Panels</p>	<p>No visible damage or missing components.</p>	
<p>Fenders</p>	<p>No visible damage or missing components</p>	
<p>Hand Rails</p>	<p>No visible damage or missing components</p>	
<p>Exterior Lights</p>	<p>All lights operational</p>	
<p>General Appearance #1</p>		







General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		







General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		







Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	







Control Station		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Mirrors		
Glass	No visible damage or missing components	
Cab Doors	No visible damage or missing components	
Seat/Armrests	No visible damage or missing components	
Hydraulic Controls	★★★★☆	
Steering Control	★★★★☆	







<p>Drivetrain Controls</p>	<p>★★★★☆</p>	
<p>Warning Lights</p>	<p>Operational</p>	
<p>Gauges</p>	<p>Operational</p>	
<p>Hour Meter</p>	<p>0 hrs, Inoperable hour meter</p>	
<p>Limited Function Check</p>	<p>The main components are in place and operational as noted.</p>	
<p>Control Station #1</p>		








Engine		
Item	Assessment	Photo
Emission Label		
A/C Compressor	In place; ambient temperature too cold to check operation	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Engine - Left Side		

<p>Engine - Right Side</p>		
<p>DEF / AdBlue Tank</p>		
<p>Limited Function Check</p>	<p>After jump starting, the engine ran. The engine would not re-start after shutting down without jump starting.</p>	
<p>Engine #1</p>		
<p>Engine #2</p>		
<p>Engine #3</p>		
<p>Engine #4</p>		







Engine #5		
Engine #6		
Engine #7		
Engine #8		
Engine #9		
Engine #10		







Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Transmission	★★★☆☆ Operational	
Inching Brake	Operational	
Front Drive Axle	★★★☆☆	
Final Drives	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★ ★ ★ ☆	
Valves	★ ★ ★ ☆	
Hydraulic Tank	★ ★ ★ ☆	
Hoses (Hydraulics)	★ ★ ☆ ☆ Right side shift hose broken	
Steering Cylinders	★ ★ ★ ☆	
Mast Lift Cylinders	★ ★ ★ ☆	








Mast Tilt Cylinders	★★★★☆	
Side Shift Cylinder	★★★★☆	
Fork Positioning Cylinder (on fork carriage)	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		








Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		
Hydraulics #10		


Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Mast/Boom Condition	★★☆☆ Heavy wear	
Chain / Tensioners	★★☆☆ Heavy wear	
Carriage Rollers and Guides	★★☆☆	
Load Back Rest	★★☆☆	
Side Shift	★★☆☆	
Forks	★★☆☆ Broken tip	

Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Park Brake	★★★★☆ Held against power	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Left Front Tire	No visible defects	
Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	

Tire Condition		
Wheel Condition	No visible damage or missing components	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		

Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		

Chassis #13		
Chassis #14		
Chassis #15		
Chassis #16		
Chassis #17		
Chassis #18		
Chassis #19		

Chassis #20		
Chassis #21		

Buy this item and view more at www.truckplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved