



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
10/30/2020	GC713066	

INSPECTOR: 5932
INSPECTION ID
129684

Year	2016	Make	PREVOST
Model	H3-45	VIN	2PCH33490GC713066

SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	BLUE

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13
Eng Serial:	0131112035
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	149"
Overall Width:	102"

Engine Options B	
Odometer:	370888
Hub odometer:	NA
ECU HP:	500
ECU Miles:	370888
Eng Hours:	11938

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	210

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	BLUE

Axle / Susp Options	
WheelBase (In):	316
Rear Ratio:	2.50
F Axle (lbs):	16,500
R Axle (lbs):	14,000
GVWR (lbs):	53,000
Suspension:	AIR RIDE
Tag Axle Capacity:	22,500
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	No
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	3000/4000
Trans Speed:	12

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	5
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additional comments:	
NA	



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 10/30/2020 VIN (LAST 8) GC713066 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
129684

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes

Steer Axle Brakes:	50%	50%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		3 / 32nd LUG / R1	7 / 32nd LUG / R1
RIGHT	8 / 32nd HIGHWAY / V 	 	 
FRONT		4 / 32nd LUG / R1	/ 32nd /
LEFT	 7 / 32nd HIGHWAY / V	8 / 32nd LUG / R1  	/ 32nd /  
		5 / 32nd LUG / R1	6 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
10/30/2020	GC713066	

INSPECTOR: 5932
INSPECTION ID
129684

CONDITION REPORT

	Engine Compartment Area	COMMENTS
	Operational Test	COMMENTS
	In Cab Inspection	COMMENTS
	Outside Inspection	COMMENTS
X	Paint Condition & Physical Damage	
	Under Vehicle Inspection	COMMENTS
	Tires/Wheels/Brakes	COMMENTS
X	Tires/Wheels	6 BAD TIRES
Additional Services		Requested
		Status
		Comments



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
10/30/2020	GC713066	

INSPECTOR: 5932
INSPECTION ID
129684

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Paint Condition & Physical Damage	X
Tires/Wheels	X 6 BAD TIRES
FRONT BUMPER	DAMAGED
ENTRY DOOR LOWER MLDG	DAMAGED
WINDSHIELD SHADE BRKT	DAMAGED
RIGHT SIDE VENT DOOR	DAMAGED
RIGHT ENGINE DOOR	DAMAGED
BATTERY DOOR	DAMAGED
RIGHT SIDE FLARE	DAMAGED
LEFT FRONT DOOR MLDG	DAMAGED
# 1 RT CARGO DOOR	DAMAGED
# 4 RT CARGO DOOR	DAMAGED
REAR BUMPER	DAMAGED

COMMENTS:
THE BUS WAS INSPECTED AT REPO YARD. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE FRONT BUMPER, ENTRY DOOR, RIGHT SIDE, LEFT SIDE, REAR BUMPER AND SIX TIRES.



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 10/30/2020 VIN (LAST 8) GC713066 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
129684



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO
BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE	VIN (LAST 8)	PO NUMBER
10/30/2020	GC713066	


INSPECTOR: 5932
INSPECTION ID
129684



FLOOR OF BUS, FRONT TO
BACK



INSIDE OF BUS, BACK TO
FRONT



FLOOR OF BUS, BACK TO
FRONT



INSIDE RESTROOM #1



SEATS




LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

INSP DATE 10/30/2020 VIN (LAST 8) GC713066 PO NUMBER

INSPECTOR: 5932
INSPECTION ID
129684



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 15




ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 18



J PRO SCREEN