



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14159141 - 2019 Volvo A25G Articulated Dump Truck



Item Details:

- Features: Air Conditioner, Rear View Camera, 2018 US EPA Label, Requires Diesel Exhaust Fluid, Steel Body Liner
- Meter Reading: 5,608 Hours
- Serial #: VCE0A25GJ00742299
- Inspection Completed: 4/14/25

Shipping Details:

- Location Georgia (Atlanta area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Already onsite

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


Item	Assessment	Photo
Chassis #14		
Chassis #13		
Chassis #12		

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	VCE0A25GJ00742299	
Paint	Damage	

Body Panels	Grille damaged	
Mud Flaps	Left damaged	
Steps	Left cab steps bent, Right cab steps bent	
Hand Rails	No visible damage or missing components	
Exterior Lights	2 Inoperable / damaged / missing	
Articulated Dump* # 1		
Articulated Dump* # 2		

Articulated Dump* # 3		
Articulated Dump* # 4		
Articulated Dump* # 5		
Articulated Dump* # 6		
Articulated Dump* # 7		
Articulated Dump* # 8		
Articulated Dump* # 9		


Articulated Dump* # 10




Safety

Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	


Control Station


Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	Cab door cracked	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter / Odometer	5608 hrs	
Air Conditioner	Operational	
Heater	Operational	

Limited Function Check	The main components are in place and operational as noted. Engine does not shut down with key in the off position, only with estop	
Articulated Dump* # 1		
Articulated Dump* # 2		
Articulated Dump* # 3		
Articulated Dump* # 4		
Articulated Dump* # 5		
Articulated Dump* # 6		

Articulated Dump* # 7		
Articulated Dump* # 8		

Engine		
Item	Assessment	Photo
Engine	2018 US EPA Label, Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		

Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	After jump starting, the engine ran. The engine would not re-start after shutting down without jump starting.	
Engine #1		
Engine #2		
Engine #3		
Engine #4		

Engine #5



Engine #6




Engine #7



Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★★★☆	
Transfer Case / Drop Box	★★★★☆	
Steer Axle	★★★★☆	
Center Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics


See photos for condition

Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Cylinders	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	


Hydraulics #1		
Hydraulics #2		


Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Oscillating Hitch	★★★★☆	
Frame Condition	★★★★☆	
Suspension Cylinders	★★★★☆ Not visible	
Suspension Pivot Points	★★★★☆	
Limited Function Check	The main chassis components functioned during a limited check.	
Master Cylinder/Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	

Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Left Front Tire	★★★★☆ Michelin XADN+ 23.5R25 29/32" Tread Depth Has cuts in the side wall	 A close-up photograph of the left front tire of a yellow machine. The tire is a Michelin XADN+ 23.5R25 29/32" model. It shows significant wear, including cuts in the side wall and a visible tread pattern.
Left Middle Tire	★★★★☆ Galaxy LDSR 300 23.5R25 29/32" Tread Depth Has cuts in the side wall, tread has missing chunks	 A photograph showing the left middle tire of a yellow machine. The tire is a Galaxy LDSR 300 23.5R25 29/32" model. It shows significant wear, including cuts in the side wall and missing chunks of tread.
Left Rear Tire	★★★★☆ Michelin XADN+ 23.5R25 28/32" Tread Depth	 A photograph showing the left rear tire of a yellow machine. The tire is a Michelin XADN+ 23.5R25 28/32" model. It shows significant wear, including cuts in the side wall and a visible tread pattern.
Right Rear Tire	★★★★☆ Michelin XADN+ 23.5R25 29/32" Tread Depth	 A photograph showing the right rear tire of a yellow machine. The tire is a Michelin XADN+ 23.5R25 29/32" model. It shows significant wear, including cuts in the side wall and a visible tread pattern.
Right Middle Tire	★★★★☆ Michelin XADN+ 23.5R25 31/32" Tread Depth Has a repair patch	 A photograph showing the right middle tire of a yellow machine. The tire is a Michelin XADN+ 23.5R25 31/32" model. It shows significant wear, including cuts in the side wall and a visible tread pattern.
Right Front Tire	★★★★☆ Michelin XADN+ 23.5R25 28/32" Tread Depth	 A photograph showing the right front tire of a yellow machine. The tire is a Michelin XADN+ 23.5R25 28/32" model. It shows significant wear, including cuts in the side wall and a visible tread pattern.

Wheel Condition	No visible damage or missing components	
Bed Body	★★★★☆	
Bed Liner	★★★★☆	
Bed Pads	★★★★☆	
Hinge Points	★★★★☆	
Limited Function Check	The main chassis components were operational in a limited check., Audible air leak	
Chassis #1		

Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved