



Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/fANibGopKJZggQDum/full\\_report\\_0033045\\_fANibGopKJZggQDum.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/fANibGopKJZggQDum/full_report_0033045_fANibGopKJZggQDum.pdf?view)

**NOTE:** By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2016
Make	Vogele
Model	Vision 5100-2
Serial Number	13820204
Type	Paver
Date Of Inspection	8/20/2021
Location of Inspection	JJ Kane Auctioneers; 3020 Commercial Rd, Fort Wayne, IN 46809
Attachment	NA
Engine MFR	Not Visible
Controls	Standard
Hours	5470
Visual Inspection	Clean
Operational Test	Passed - Operational
Left Track Condition	Good Condition
Left Track Brand	Not Visible



**Aspen Field Services**

Job #: 33045 /

Serial #: 1382.0204

2016 VOGELE VISION 5100

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

Inspection Details Cont'd	
Left Track Depth Measurement	29/32"
Left Track Tread Depth Percentage	Under 50%
Left Track Sprocket	Good Condition
Left Track Rollers	Good Condition
Left Track Idler	Good Condition
Right Track Condition	Good Condition
Right Track Brand	Not Visible
Right Track Tread Depth Measurement	24/32"
Right Track Tread Depth Percentage	Under 50%
Right Track Sprocket	Good Condition
Right Track Rollers	Good Condition
Right Track Idlers	Good Condition
Mismatched Tracks	No
Material Hoppers Operations	NA - See Notes
Operator Seat	Tear
Passenger Seat	Tear
Engine Door	Good Condition
Engine Compartment	Not Visible
Muffler	Good Condition
Intake Screen	Good Condition
Customer Decals Visible on Unit	Yes
Working Lights	NA Unable to Verify
Rear Working Lights	NA Unable to Verify
Hopper Operations	NA Unable to Verify
Comments	The machine needed to be jump started in order to turn on. The site did not know how to operate the hopper, turn on the lights, or open the engine compartment. The hours screen was significantly scratched, but the hours can be seen.

Inspection Details Cont'd