



Aspen Field Services

Job #: 33825 /

Serial #: NDC10007

CAT 352F EXCAVATOR

For more information, visit:

wellsfargo.com/equipseller



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/RruLnSHJeJbj2dJoR/full_report_0033825_RruLnSHJeJbj2dJoR.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	Not Available
Make	CAT
Model	352F
VIN	CAT0352FPNDC10007
Type	Excavator
Inspection Date	09/16/2021
Location of Business	JJ Kane Auctioneers 95 3rd St NE, Graysville, AL, 35073, USA
Hours	5992
Operational Test	Passed - Operational
Attachment	Missing
Enclosed Cab	Yes
Controls	Standard
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes



Aspen Field Services

Job #: 33825 /

Serial #: NDC1007

For more information, visit:

wellsfargo.com/equipmentseller

CAT 352F EXCAVATOR

Inspection Details Cont'd	
Cab Heat Condition	Good Condition
Backup Camera	Yes
Backup Camera Condition	Good Condition
Keyless Start	No
Visual Inspection	Fair
Bucket Cylinder	Missing
Boom Arm	Good Condition
Boom Arm Cylinder	Good Condition
Stick Attachment	Missing
ROPS Condition	Good Condition
Cab Glass Condition	Good Condition
Front Door	Good Condition
Seat Condition	Good Condition
Muffler	Not Available
Intake Screen	Good Condition
Headlights	None
Working Lights	Operational - See Notes
Engine Compartment	Clean
Engine Manufacturer	Not Available
Active Warnings	None
Interior	Good Condition
Left Track Condition	Good Condition
Left Track Brand	Not Available
Left Track Sprocket	Good Condition
Left Track Idler	Good Condition
Left Track Rollers	Good Condition
Left Track Tread Depth Percentage	NA - Metals Tracks
Right Track Condition	Good Condition
Right Track Brand	Not Available
Right Track Sprocket	Good Condition
Right Track Idler	Good Condition
Right Track Rollers	Good Condition
Right Track Tread Depth Percentage	NA - Metals Tracks
Comments	The VIN number provided was slightly different. The stick or dipper has been removed and is missing from the boom arm. The bucket cylinder is missing. No attachments with unit. Boom arm light not operational

Inspection Details Cont'd