



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15396135 - 2024 Tigercat 620H 4x4 Skidder



Item Details:

- Features: Air Conditioner, Joystick Steering, Air Ride Seat, Sweeps, Screens, Two-Position Station, 2023 US EPA Label, Requires Diesel Exhaust Fluid, Blade, Tiger cat Grapple, Duals
- Meter Reading: 3,617 Hours
- Serial # : 6209680
- Inspection Completed: 6/16/26

Shipping Details:

- Location Georgia (Atlanta area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	6209680	
CE Mark	No CE mark found	
Hour Meter / Odometer	3617 hrs	
v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		
v3 General Appearance # 4		
v3 General Appearance # 5		

v3 General Appearance # 6		
v3 General Appearance # 7		
v3 General Appearance # 8		
v3 General Appearance # 9		
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders		

Hand Rails		
Glass		
Exterior Lights	Some not operational, Rear lights lights are not operational	

Safety


Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station

Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Seats/Armrests		
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★☆☆ Loose switch	
Dash Console	★★★★	
Engine Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational, Multiple alarms on the screen light stays on	
Gauges	Operational	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	2023 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	

Oil Leaks	Cannot verify oil leaks, engine bay is full of water	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	☆☆☆☆ Operational, Not visible	
Front Drive Axle	☆☆☆☆	
Rear Drive Axle	☆☆☆☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics

See photos for condition

Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆ No access	
Hydraulic Tank	★★★★☆	
Hoses/Lines - Skidder	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Grapple Cylinders	★★★★☆	
Blade Lift Cylinders	★★★★☆	

Steering Cylinders	★ ★ ★ ☆	
Hydraulic Motors	★ ★ ★ ☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		

Hydraulics #6



Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Grapple Boom Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆	
Boom to Grapple Pins and Bushings	★★★★☆	
Limited Function Check	The main chassis components were operational in a limited check.	

Undercarriage

Item	Assessment	Photo
Undercarriage #1		 A close-up photograph of a large, heavy-duty treaded tire, likely from a bulldozer, showing the tread pattern and the yellow rim.
Undercarriage #2		 A close-up photograph of a tire rim and the lower portion of the tread, showing some wear and a dark, possibly oily, substance on the rim.
Undercarriage #3		 A close-up photograph of a heavily rusted metal component, possibly a bracket or a part of the undercarriage, showing significant corrosion and debris.
Undercarriage #4		 A close-up photograph of a metal bracket or support structure, showing signs of wear, rust, and a dark, possibly oily, substance on the surface.
Undercarriage #5		 A close-up photograph of a tire rim and the lower portion of the tread, showing some wear and a dark, possibly oily, substance on the rim.
Undercarriage #6		 A close-up photograph of a tire rim and the lower portion of the tread, showing some wear and a dark, possibly oily, substance on the rim.

Undercarriage #7		
Undercarriage #8		
Undercarriage #9		
Undercarriage #10		
Undercarriage #11		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydrostatic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Tire Brands	N/A, Cannot verify brand	
Left Front Tire		
Left Rear Tire	All tires have damage	

Right Rear Tire		
Right Front Tire		
Wheel Condition	★★☆☆ Some wheel damage	
Wheel Studs, Nuts, Lugs	★★★☆☆	

Specialty		
Item	Assessment	Photo
Winch	★★☆☆ Not operationally checked	
Grapple	★★☆☆	
Blade Condition	★★☆☆ Damaged blade	
Specialty #1		
Specialty #2		
Specialty #3		

Specialty #4		
Specialty #5		
Specialty #6		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved