



















 **KENWORTH**

 **KENWORTH**











CAUTION
Do not get too close to the mixer drum. It can rotate and cause injury.

KENWORTH

KW KENWORTH













13.8V

22:26

Press  to access

112 °F

Menu

Systems Check

Completed 13 of 13

13 Systems are OK



0 Critical Issues



0 Non-Critical Issues



Access MENU to see more details

211,527.1 MI

Trip 751.6 MI

H 66.6 MI

N



ABS

Make

Model

Software Version

211,527.1 MI



PACCAR

CX15


PACCAR
437-1007











WARNING
Do not touch the exhaust manifold or other hot engine components. The temperature of these components can be high enough to cause serious burns or death. Always use proper safety techniques when working on the engine. For more information, see the operator's manual.

CAUTION
Do not touch the alternator or other electrical components. The temperature of these components can be high enough to cause serious burns or death. Always use proper safety techniques when working on the engine. For more information, see the operator's manual.

Part No. 80607610

RCEXH0912X

X15 500V

fig. 01/24

RPM 550-800

8NY5V2K521S830G13



terminal distribution
Generators Electric
W-585-8025 or

7000-71018 TMI

Part
Heater



Ind. Lamp Flashes

Overheat Rapid
High Temp 1
Low Oil Pressure 2
Air Filter Clogged 3

On



Off



Stop



35 Amp 2 Pole
AC Breaker

MIN

Cold



Hot



MAX

Battery Charge Line