



Aspen Field Services

Job #: 27920 /

Serial #:

WNCR0801THAA00277

For more information, visit:

wellsfargo.com/equipmentseller

WACKER NUESON RC70 ROLLER



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/bNhdDvFiQgGxyaAuj/full_report_0027920_bNhdDvFiQgGxyaAuj.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Wacker Neuson
Model	RC 70
Serial Number	WNCR0801THAA00277
Type	Roller
Inspection Date	2/15/2021
Location of Business	JJ Kane Auctioneers - 14354 Dearborn Ave, South Beloit, IL, 61080, USA
Attachment(s)/Accessory(s)	Blade Serial Number Not Available
Enclosed Cab	No
Engine MFR	Not Visible
Controls	Standard
Hours	Not Available
Cab A-C	No
Cab Heat	No
Backup Camera	None



Aspen Field Services

Job #: 27920 /

Serial #:

WNCR0801THAA00277

For more information, visit:

wellsfargo.com/equipmentseller

WACKER NUESON RC70 ROLLER

Inspection Details Cont'd	
Keyless Start	No
Visual Inspection	Clean
Operational Test	Does Not Start
Back Right Tire Part Number	Not Available
Back Right Tire Depth Percentage	Above 50 %
Back Right Tire Condition	Good Condition
Back Left Tire Part Number	Not Available
Back Left Tire Depth Percentage	Above 50%
Back Left Tire Condition	Good Condition
Mismatched Tires	No
Tilt Cylinders	Good Condition
Articulation Pendulum	Not Accessible
Seat	Good Condition
Tailgate Lights	NA
Working Lights	NA
Front Door	NA
Side Glass Complete	NA
Rear Door	Opens and Closes
Mufflers	Good Condition
ROPS Condition	Good Condition
Cab A-C Condition	NA
Cab Heat Condition	NA
Intake Screen	Good Condition
Interior	Good Condition
Engine Compartment	Dirty
Customer Decals Visible on Unit	No
Hydraulic Hoses	Good Condition - No Leaks
Comments	This machine will not start. Due to it's current condition we are unable to verify the standard operations on this machine. The base of the steering wheel column is missing and the wiring is exposed. Due to the condition of the steering wheel column additional unknown controls may be missing.

Inspection Details Cont'd