



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #15681455 - 2022 CMI C-175 TwisterII Tracked Mulcher Tractor



Item Details:

- Features: Enclosed Cab, Air Conditioner, Joystick Steering, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 22 in Track Belts, Denis Cimaf 6 ft 3 in, Forestry mower, Winch
- Meter Reading: 1,928 Hours
- Serial # : CMI175CUD204504
- Inspection Completed: 8/3/26

Shipping Details:

- Location Florida (Lakeland-Winter Haven area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Steps/Ladders		
Hand Rails		
Glass		
Exterior Lights	Not operational	

Safety

Item	Assessment	Photo
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station

Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Seats/Armrests		

Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational	
Gauges	Operational	
Air Conditioner	Operational	

Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	2022 US EPA Label, Requires Diesel Exhaust Fluid	
v2 Engine # 1		
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Drive Motors	★★★☆☆	
Final Drives	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		

Hydraulics

See photos for condition

Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Loader Lift Cylinders	★★★★★	
Bucket Tilt Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		

Undercarriage

Item	Assessment	Photo
Undercarriage #1		 A side view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.
Undercarriage #2		 A close-up view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.
Undercarriage #3		 A close-up view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.
Undercarriage #4		 A side view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.
Undercarriage #5		 A close-up view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.
Undercarriage #6		 A close-up view of a yellow tracked undercarriage component, showing the track and the frame. The component is mounted on a gravel surface. A watermark "IRON" is visible in the bottom right corner.

Undercarriage #7		
Undercarriage #8		
Undercarriage #9		
Undercarriage #10		
Undercarriage #11		
Undercarriage #12		
Undercarriage #13		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Frame Condition	★★★★☆	
Belly Pans	★★★★☆	
Lift Arm Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆ Heavy movement	
Quick Coupler to Arms Pins	★★★★☆ Heavy movement	
Limited Function Check	The main chassis components were operational in a limited check.	
Chassis #1		

Chassis #2



Undercarriage

Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grousers) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.

Item	Assessment	Photo
Roller Frames	☆☆☆☆	
Grouser Height Measurement	Left side: 44 mm, Right side: 42 mm	
Track Tensioners	No visible damage	
Carrier Rollers		
Front Idler Wear		
Track Rollers		
Sprockets	Left sprocket has major damage Track bushing have extreme wear	

Specialty

Item	Assessment	Photo
v2 Front Attachment # 1		
v2 Front Attachment # 2		
v2 Front Attachment # 3		
v2 Front Attachment # 4		
v2 Front Attachment # 5		
v2 Front Attachment # 6		

v2 Front Attachment # 7		
v2 Front Attachment # 8		
Mulcher	 Worn teeth, Damaged teeth	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved