

#### BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 09/22/2020 HC713561

Year	2017 Make	PREVOST
Model	H3-45 VIN	2PCH33498HC713561

Model	H3-45	VIN	2PCH33498HC713561
SPECIFICATION WORKSHEET			
Interior Options Interior Color:	BLUE	Steering Options Power Steering?:	Yes

Engine Options A		Overall Condition	
Eng Make:	VOLVO	Overall Length:	45'
Eng Model:	D13J435P	Overall Height:	146"
Eng Serial:	013157120	Overall Width:	102"
Eng HP:	435		
Cruise:	Yes		
Clean air idle:	Yes		

Engine Options B	
Odometer:	NA
Hub odometer:	NA
ECU HP:	NA
ECU Miles:	203022
Eng Hours:	NA

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	216

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	316
Rear Ratio:	4.25
F Axle (lbs):	16,500
R Axle (lbs):	14,000
GVWR (lbs):	53,000
Suspension:	AIR RIDE
Tag Axle Capacity:	22.500
Rear Axle Model:	UNK
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	No
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	VOLVO
Trans Model:	I-SHIFT
Trans Speed:	12

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	5
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	Yes
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA



Brakes Options ABS:

HYD:

AIR:

DISK:

DRUM:

Brake Plates:

# DEKRA Services Inc. Customer Service 770-257-0107

YES

NO

YES

YES

NO

FRONT N / REAR N

BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561

INSPECTOR: 5932 INSPECTION ID 126434

Brakes			
Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Front]		Tires [Rear]	
Size:	315/80 R22.5	Size:	315/80 R22.5
Wheels:	ALUMINUM	Wheels:	ALUMINUM
Detail:		Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		7 / 32nd LUG / R1	10 / 32nd LUG / R1
RIGHT	14 / 32nd HIGHWAY / V		
	THE STATE OF THE S		
FRONT		7 / 32nd LUG / R1	/ 32nd /
FRONT		4 / 32nd LUG / R1	/ 32nd /
LEFT	12 / 32nd HIGHWAY / V		
		4 / 32nd LUG / R1	7 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend
H = HIGHWAY L = LUG



BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561 |

INSPECTOR: 5932 INSPECTION ID 126434

CONDITION REPORT

	Engine Compartment Area		COMMENTS
	Operational Test		COMMENTS
	In Cab Inspection		COMMENTS
Х	Windshield, Door & Any Other Glass	LEFT WINDSHI	ELD DAMAGED
	Outside Inspection		COMMENTS
Х	Mirrors	LEFT MIRROR	COVER DAMAGED
	Under Vehicle Inspection		COMMENTS
	Tires/Wheels/Brakes		COMMENTS
Χ	Tires/Wheels	5 BAD TIRES	

	Additional Services	Requested	Status	Comments
--	---------------------	-----------	--------	----------



#### **BUS**

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561

INSPECTOR: 5932 INSPECTION ID 126434

## RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS	
Windshield, Door & Any Other Glass	X   LEFT WINDSHIELD DAMAGED	
Mirrors	X   LEFT MIRROR COVER DAMAGED	
Tires/Wheels	X   5 BAD TIRES	
FRO NT BUMPER	DAMAGED	
ENTRY DOOR MLDG	DAMAGED	
RIGHT FRONT FLARE	DAMAGED	
# 1 CARGO DOOR	DAMAGED	
# 2 CARGO DOOR MLDG	DAMAGED	
# 3 CARGO DOOR MLDG	DAMAGED	
# 4 CARGO DOOR MLDG	DAMAGED	
# 4 CARGO DOOR	DAMAGED	
RIGHT REAR FLARE	DAMAGED	
BATTERYDOOR	DAMAGED	
RIGHT REAR VENT DOOR	DAMAGED	
RIGHT SIDE CENTER PILLAR	DAMAGED	
LEFT FRONT FLARE	DAMAGED	
# 1 LEFT CARGO DOOR	DAMAGED	
# 2 LEFT CARGO DOOR	DAMAGED	
# 3 LEFT CARGO DOOR	DAMAGED	
# 4 CARGO DOOR	DAMAGED	
# 4 CARGO DOOR LOWER MLDG	DAMAGED	
# 5 CARGO DOOR	DAMAGED	
# 5 CARGO DOOR LOWER MLDG	DAAMGED	
LEFT REAR FLARE	DAMAGED	
LEFT REAR VENT DOOR	DAMAGED	
LEFT SIDE PANEL	DAMAGED	
FRO NT PANEL	DAMAGED	
INSTRUMENT PANEL	DIAGNOSTIC DISPLAY NOT WORKING	

#### COMMENTS:

THE BUS WAS INSPECTED AT AZ BUS IN COLTON. THE UNIT HAD TO BE JUMPED IN ORDER TO GET TO START. ONCE THE BUS GOT STARTED IT WAS IN GOOD WORKING CONDITION. THERE WAS DAMAGE TO THE FRONT PANEL, ENTRY DOOR, RIGHT SIDE, LEFT SIDE, LEFT MIRROR, LEFT WINDSHIELD AND FIVE TIRES. ALSO DASH DISPLAY NOT WORKING.



## BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER | 09/22/2020 | HC713561



































BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 09/22/2020 HC713561




























**ENGINE COMPARTMENT RIGHT SIDE** 



SIDE













BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561



































BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561




































BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/22/2020 | HC713561







