

# Jacobsen GP400



([https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786432/big\\_etc71712ede58ea55ba36aa3e6dd4bba.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786432/big_etc71712ede58ea55ba36aa3e6dd4bba.jpg))



([https://panda-assets-](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786432/big_etc71712ede58ea55ba36aa3e6dd4bba.jpg)

[live.s3.amazonaws.com/uploads/document/image/3786432/big\\_etc71712ede58ea55ba36aa3e6dd4bba.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786432/big_etc71712ede58ea55ba36aa3e6dd4bba.jpg))



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786433/big\_8f239881576fd826f4e749224e4fb40e.jpg)



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786434/big\_19db155ffa68a4075929c2a658701ae.jpg)



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786435/big\_94c0d102407ee866476ba009d7ea937d.jpg)



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786436/big\_956a487ad2c45f9870342ecff34f1cbf.jpg)



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786437/big\_74891e6a6ec08fd59343e7582c3d2cc0.jpg)



(https://panda-assets-

live.s3.amazonaws.com/uploads/document/image/3786438/big\_7317d1b7bff7d7c2dc6b4daa46c5c17e.jpg)



([https://panda-assets-](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786439/big_bd446d58574a0938d3c70c560bb40a2a.jpg)

[live.s3.amazonaws.com/uploads/document/image/3786439/big\\_bd446d58574a0938d3c70c560bb40a2a.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786439/big_bd446d58574a0938d3c70c560bb40a2a.jpg))



([https://panda-assets-](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786440/big_d8d52e1012b83382c01929d0dbf299f5.jpg)

[live.s3.amazonaws.com/uploads/document/image/3786440/big\\_d8d52e1012b83382c01929d0dbf299f5.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786440/big_d8d52e1012b83382c01929d0dbf299f5.jpg))



([https://panda-assets-](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786441/big_c3ae90e37e3aba9d1dd750a2f3be3d0a.jpg)

[live.s3.amazonaws.com/uploads/document/image/3786441/big\\_c3ae90e37e3aba9d1dd750a2f3be3d0a.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786441/big_c3ae90e37e3aba9d1dd750a2f3be3d0a.jpg))



([https://panda-assets-](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786442/big_3f23cbdae29804319d086db39e832ef0.jpg)

[live.s3.amazonaws.com/uploads/document/image/3786442/big\\_3f23cbdae29804319d086db39e832ef0.jpg](https://panda-assets-live.s3.amazonaws.com/uploads/document/image/3786442/big_3f23cbdae29804319d086db39e832ef0.jpg))

## SPECIFICATIONS

---

**Hours:** 2116

---

**Year/Make/Model:** Jacobsen GP400

---

**S/N:** 6270610836

---

**Location:** Locust, NC

<https://reports.assetiqfinancial.com> Copy text

# Full Specs

## IDENTIFICATION

---

**Description:** Needs new battery. 15 Blade Reel

---

**S/N:** 6270610836

---

**Year, Make, Model:** Jacobsen GP400

---

**Hours:** 2116

---

## APPRAISAL

---

**Low Appraisal Value:** \$0.00

---

**High Appraisal Value:** \$0.00

---

**Repair Cost:** \$0.00

---

## EQUIPMENT INSPECTION

---

**Inspection Date:** 2021-02-12

---

**Hours (If Applicable):** 2116

---

**Front Body Panels:** Average Condition (Some Scratches)

---

**Seat / Frame:** Average Condition (Minor Tear)

---

**Canopy / Cab:**

---

**Gauges:** Normal Working Condition

---

**Machine Frames:** Normal Condition

---

**Reels / Head:** 15 Blade

---

**Engine Type:** Gasoline

---

**HP:**

---

**PTO/Transmission:** Normal Working Condition

---

**Electric Motors:**

---

**Additional Comments:**

Unit will crank and run after being jumped. Needs new battery. Front right tire does not match other tires. Front left rim is bent. Heavy rust on reels and rollers. Reels will not lift, lower, or engage. Hydraulic warning light was on, added hydraulic fluid but still had the same results.

---

**Wheel Drive:** 2WD

---

**Accessories Included:**

---

**Rear Body Panels:** Average Condition (Some Scratches)

---

**Wheels / Tires / Tracks:** Poor Condition {No Tread}

---

**Rollers / Reels / Decks Attachments:** Poor Condition (Rusty)

---

**Machine Controls:** Not Working

---

**Brakes:** Average Condition (Normal Wear)

---

**Tines:**

---

**MFG:**

---

**Engine Condition:** Bad Battery

---

**Drive Belts:**

---

**Hydraulics:**

---