

2019 Volvo EW60E

Unit: VCEEW60EC00312206

[Download Reconditioning Printout](#)



[VIEW ALL PHOTOS](#)

UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

WELLS FARGO
275 ROUTE 52
NORTH FRANKLIN, CT 06254

[FULL SPECS](#) [TIRES](#) [RECONDITIONING](#)

GENERAL APPEARANCE

Serial / VIN
VCEEW60EC00312206

Pre-Operational Checks
Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid. Low engine coolant

Body Panels Condition
No visible damage or missing components Door dented

Steps/Ladders
No visible damage or missing components

SAFETY

Travel Alarm
Operational

Seat Belts
Operational

Swing Brake
Operational

Current Operator/Maintenance Manual
Yes

CONTROL STATION

Seats/Armrests
No visible damage or missing components

Cab Doors
No visible damage or missing components Cab door dented

Hydraulic Controls Rating
Good

Dash Console Rating
Good

Fault Indicator Lights
Operational

Hour Meter/Odometer (Start)
1965.6 hrs

Cab Air Conditioner
The ambient temperature is too cold to check

Limited Function Check (Control Station)
The main components are in place and operational as noted.

ENGINE

Emission Certification Label
Tier 4

Blow by @ Idle (subjective visual observation)
No noticeable vapor or pressure

Exhaust System
No visible damage or missing components

Oil Leaks
No dripping leaks

Cooling System Leaks
No dripping leaks

EPA Label
2019 US EPA Label

DRIVETRAIN

Drive Motors Rating
Good

Rear Drive Axle
Good

Drive Line
Good

Limited Function Check (Drivetrain-Track)
The main chassis components functioned during a limited check.

CHASSIS

Boom/Stick Details
Swing Boom, 5 ft 3 in Stick, Auxiliary Hydraulic Plumbing, Backfill Blade, Dependencies Excavator:

Stick Condition Rating
Good

Boom Base Pin and Bushings Rating
Good

Pin and Bushings Boom to Stick Rating
Good

Turtable Bearing Rating
Good

Tires
12-16.5 Tires

LOGISTICS INFORMATION

Shipping Dimensions
19 ft 2 in Long x 6 ft 2 in Wide x 10 ft Tall

FEATURES

Features
Air Conditioner, Rear View Camera

HYDRAULICS

Pumps (Hydraulics) Rating
Good

Hydraulic Tank Rating
Good

Hoses/Lines Excavator Rating
Good

Swing Motor Condition Rating
Good

Boom Swing Cylinders
Good

Stick Cylinder Rating
Good

Thumb Cylinder
Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

SPECIALTY

Front Attachment
Hydraulic Quick Coupler, 22 in Digging Bucket, Hydraulic Thumb

Excavator Bucket Rating
Good

Teeth / Adapters Rating
No visible damage or missing components

Quick Coupler Rating
Operational

Thumb Condition
Good

WHEEL EXCAVATOR TIRES

Steering Linkage
Good

Limited Function Check (Rubber Tire)
The drivetrain was operational.

Park Brake
Good

Left Front Tire
Size: 12-16.5 Brand: Tiron Model: L-2 Tread Depth: 15/32

Right Rear Tire
Size: 12-16.5 HS656 Brand: Tiron Model: L-2 Tread Depth: 13/32

Wheel Condition
No visible damage or missing components

CE Mark
No CE mark found

Paint
No visible damage

Cab/Canopy Overhead Structural Framework
No visible damage

Hand Rails
No visible damage or missing components

Horn
Operational

Safety Lock Out/Stop
Operational

Current Safety Manual
No

Glass
No visible damage or missing components

Steering Control Rating
Good

Drivetrain Controls Rating
Good

Oil Pressure
The fault indicator shuts off after the engine oil pressure rises.

Gauges
Operational

Hour Meter/Odometer
1966 hrs, Operational hour meter

Cab Heater
Operational

A/C Compressor
Operational

Starter
Operational

Radiator Rating
Good

Fuel Leaks
No dripping leaks

Limited Function Check (Engine)
The engine started and ran.

Front Drive Axle
Good

Rear Axle Oscillating Pin
Good

Final Drives
Good

Boom Condition Rating
Good

Swing Tower Pivot Rating
Good

Pin and Bushings Boom to Stick Condition
Good

Pin and Bushings Stick to Bucket Rating
Good

Limited Function Check (Chassis)
The main components were operational in a limited check.

General Shipping Information
Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? Yes: Inflated Tires - Item can roll? No: Is the unit taller than 12'? No: Is the unit wider than 8'6"? No: Noticeable fluid leaks?

Valves Rating
Good

Hydraulic Control Pattern Changer Condition
Not operationally checked

Auxiliary Hydraulic Plumbing
Operational, End of stick

Hydraulic Center Swivel Rating
Good

Boom Lift Cylinder Rating
Good

Bucket Cylinder Condition
Good

Blade Lift Cylinders
Good

Excavator Bucket Condition
All lights operational

Teeth / Adapters Condition
Good

Quick Coupler Condition
Good

Blade Condition
Good

Frame Condition
Good

Brake Controls
Good

Limited Function Check (Brakes)
The brake system functioned, stopping and holding the machine.

Left Rear Tire
Size: 12-16.5 HS656 Brand: Tiron Model: L-2 Tread Depth: 13/32

Right Front Tire
Size: 12-16.5 HS656 Brand: Tiron Model: L-2 Tread Depth: 17/32