



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953

Information

Complete VIN:	2PCH33494GC713166	Request ID:	2015271113
Unit number:		Year:	2016
Make:	PREVOST	Model:	H3-45

Vehicle location

Customer:	ERIC COOLBAUGH	ZIP CODE:	21061
District:		City:	GLEN BURNIE
State:	MD	Address:	6809 RITCHIE HIGHWAY,
Phone:	8666752271	Location:	Advantage Remarketing Solutions

Inspection Request

Inspection Instructions

-



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	VIN (LAST 8)	PO NUMBER
01/28/2021		GC713166	

INSPECTOR: 5529

INSPECTION ID

135953

Year	2016	Make	PREVOST
Model	H3-45	VIN	2PCH33494GC713166

SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	GREY/ BLUE/ WOODGRAIN

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13J435P
Eng Serial:	1125889
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45FT
Overall Height:	146FT
Overall Width:	102FT

Engine Options B	
Odometer:	186,441
Hub odometer:	
ECU HP:	410
ECU Miles:	186,449
Eng Hours:	N/A

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	7
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	Yes
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	Yes
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	Yes
Other:	
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	FAIR
If Unit is not driveable or will not start, Explain:	
Any extra options or features not listed on front page and any additional comments:	

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	222

Exterior Options A	
Air Horns:	SINGLE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	314
Rear Ratio:	3.58
F Axle (lbs):	16,500
R Axle (lbs):	22,500
GVWR (lbs):	2040
Suspension:	AIR RIDE
Tag Axle Capacity:	14,000
Rear Axle Model:	
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	3000/4000 5TH GENERATION
Trans Speed:	7



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Brakes

Steer Axle Brakes:	65%	65%	(1)
Drive Axle Brakes:	65%	65%	(2)
	65%	65%	(3)
			(4)
			(5)
			(6)

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		13 / 32nd HIGHWAY / R1	/ 32nd /
RIGHT	14 / 32nd HIGHWAY / V 	 	 
FRONT		12 / 32nd HIGHWAY / R1	10 / 32nd HIGHWAY / R1
		12 / 32nd HIGHWAY / R1	10 / 32nd HIGHWAY / R1
LEFT	 15 / 32nd HIGHWAY / V	 	 
		11 / 32nd HIGHWAY / R1	/ 32nd /

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953

CONDITION REPORT

	Engine Compartment Area		COMMENTS	
X	Oil, Coolant and Other Fluid Leaks	CLASS 1 (BUILD-UP) AT CRANKCASE		
X	Exhaust & Intake Systems	SIGNS OF EXHAUST LEAK		
X	Other	FUEL FILTER NEEDS REPLACED		
	Operational Test		COMMENTS	
	In Cab Inspection		COMMENTS	
X	Windshield, Door & Any Other Glass	CRACKED WINDSHIELD		
	Outside Inspection		COMMENTS	
X	Mirrors	R/S MIRROR DAMAGED		
X	Lights and Reflectors	R/S UPPER REAR CLEARANCE LIGHT INOP.		
	Under Vehicle Inspection		COMMENTS	
	Tires/Wheels/Brakes		COMMENTS	
Additional Services		Requested	Status	Comments



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Oil, Coolant and Other Fluid Leaks	X CLASS 1 (BUILD-UP) AT CRANKCASE
Exhaust & Intake Systems	X SIGNS OF EXHAUST LEAK
Other	X FUEL FILTER NEEDS REPLACED
Windshield, Door & Any Other Glass	X CRACKED WINDSHIELD
Mirrors	X R/S MIRROR DAMAGED
Lights and Reflectors	X R/S UPPER REAR CLEARANCE LIGHT INOP.
OBD2 DATA	NOT AVAILABLE
I.D. DECALS	PRESENT

COMMENTS:



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

GC713166

VIN (LAST 8)

PO NUMBER

INSPECTOR: 5529

INSPECTION ID

135953



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS




REAR LEFT CORNER



LEFT REAR TIRES




COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO BACK



FLOOR OF BUS, FRONT TO BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953



INSIDE OF BUS, BACK TO FRONT



FLOOR OF BUS, BACK TO FRONT



INSIDE RESTROOM #1



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE COMPARTMENT
RIGHT SIDE



ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



OIL LEAKS



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



ENGINE FAMILY NUMBER



ADDITIONAL 5



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

01/28/2021

FLEET NAME

VIN (LAST 8)


PO NUMBER

GC713166

INSPECTOR: 5529

INSPECTION ID

135953



ADDITIONAL 11



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



Other



Windshield, Door & Any
Other Glass



Mirrors



Lights and Reflectors



Oil, Coolant and Other Fluid
Leaks



Exhaust & Intake Systems