



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

F2041384

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

136479

Information

Complete VIN:	YE2YC11B1F2041384	Request ID:	2015271844
Unit number:		Year:	2015
Make:	VAN HOOL	Model:	TX45

Vehicle location

Customer:	TERRY FISCHER	ZIP CODE:	92865
District:		City:	ORANGE
State:	CA	Address:	1931 NORTH BATAVIA STREET,
Phone:	7146374300	Location:	Transportation Charter Services

Inspection Request

Inspection Instructions

-



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

TX45

VIN (LAST 8)

F2041384

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

136479

Year	2015	Make	VAN HOOL
Model	TX45	VIN	YE2YC11B1F2041384

SPECIFICATION WORKSHEET

Interior Options

Interior Color:	BLUE
-----------------	------

Steering Options

Power Steering?:	Yes
------------------	-----

Engine Options A

Eng Make:	CUMMINS
Eng Model:	ISX12
Eng Serial:	NA
Eng HP:	425
Cruise:	Yes
Clean air idle:	Yes

Overall Condition

Overall Length:	45'
Overall Height:	12'
Overall Width:	102"

Engine Options B

Odometer:	485667
Hub odometer:	NA
ECU HP:	500
ECU Miles:	483892
Eng Hours:	9070

Miscellaneous

Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	No
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	Yes
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additional comments:	NA

Engine Options C

Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	231

Exterior Options A

Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options

WheelBase (In):	321
Rear Ratio:	3.42
F Axle (lbs):	7,640
R Axle (lbs):	17,640
GVWR (lbs):	54,000
Suspension:	AIR RIDE
Tag Axle Capacity:	27,575
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options

Trans Make:	ALLISON
Trans Model:	3000/4000 5TH GEN
Trans Speed:	6



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479

Brakes Options

ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes

Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Front]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]

Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		10 / 32nd LUG / R1	13 / 32nd LUG / R1
RIGHT	16 / 32nd HIGHWAY / V 	 	 
FRONT		9 / 32nd LUG / R1	/ 32nd /
		8 / 32nd LUG / R1	/ 32nd /
LEFT	 16 / 32nd HIGHWAY / V	 	 
		6 / 32nd LUG / R1	9 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479

CONDITION REPORT

	Engine Compartment Area	COMMENTS
	Operational Test	COMMENTS
X	Engine Warning System	active code
	In Cab Inspection	COMMENTS
	Outside Inspection	COMMENTS
X	Paint Condition & Physical Damage	BODY DAMAGE
	Under Vehicle Inspection	COMMENTS
	Tires/Wheels/Brakes	COMMENTS
X	Tires/Wheels	4 tires below 10/32

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

F2041384

PO NUMBER

INSPECTOR: 5932

INSPECTION ID

136479

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Engine Warning System	X active code
Paint Condition & Physical Damage	X BODY DAMAGE
Tires/Wheels	X 4 tires below 10/32
FUEL DOOR MLDG	DAMAGED (PAINT)
RIGHT SIDE # 1 CARGO DOOR	MLDG DAMAGED
RIGHT SIDE # 2 CARGO DOOR	MLDG DAMAGE
RIGHT SIDE # 2 CARGO DOOR	MLDG DAMAGE
RIGHT SIDE # 3 CARGO DOOR	MLDG DAMAGE
RIGHT SIDE # 4 CARGO DOOR	MLDG DAMAGE
RIGHT REAR WHEELHOUSE	DAMAGED
LEFT SIDE # 1 CARGO DOOR	MLDG DAMAGE
LEFT SIDE # 2 CARGO DOOR	MLDG DAMAGE
LEFT SIDE VENT DOOR	MLDG DAMAGE
LEFT SIDE CENTER PANEL	MLDG DAMAGE
LEFT SIDE WHEELHOUSE	DAMAGED
LEFT SIDE ENGINE DOOR	DAMAGED
RIGHT SIDE PANEL	DAMAGED
ROOF/LEFT WINDSHIELD PILLAR	DAMAGED

COMMENTS:



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS




FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT
DOOR



COMPLETE DRIVERS SEAT



ODOMETER



INSIDE OF BUS, FRONT TO
BACK



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479



FLOOR OF BUS, FRONT TO
BACK



INSIDE OF BUS, BACK TO
FRONT



FLOOR OF BUS, BACK TO
FRONT



INSIDE RESTROOM #1



SEATS



LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER




ENGINE COMPARTMENT
RIGHT SIDE




ENGINE COMPARTMENT LEFT
SIDE



INSIDE STORAGE
COMPARTMENTS



J PRO SCREEN



J PRO ACTIVE CODE



ADDITIONAL 1



ADDITIONAL 2



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 6



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 15



ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 18



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

02/09/2021

FLEET NAME

VIN (LAST 8)

PO NUMBER

F2041384

INSPECTOR: 5932

INSPECTION ID

136479



ADDITIONAL 19



ADDITIONAL 20



ADDITIONAL 21



ADDITIONAL 22



ADDITIONAL 23



ADDITIONAL 24



OIL LEAKS



ADDITIONAL 25