

Aspen Field Services Job #: 26507 / Serial #: A20700138

For more information, visit: wellsfargo.com/equipmentseller





Video:



PHOTOS: Click the link below to view all high resolution images https://app.aspenfieldservices.com/api/attachments/get/ jMX4b3isYK4dTuLkj.full\_report\_0026507\_jMX4b3isYK4dTuLkj.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.





Inspection Details		
Year	2017	
Make	Kalmar	
Model	DCG250-12LB	
Serial Number	A20700138	
Туре	Forklift	
Inspection Date	12/30/2020	
Location of Business	Sandbox Logistics - 9159 West Hwy 85, Dilley, TX, 78017, USA	
Attachment(s)/ Accessory(s)	None	
Mismatched Forks	No	
Bent Forks	No	
Excessive Fork Wear	No	
Fork Length (inches)	96"	
Fork Width (inches)	10"	
Fork Depth (inches)	4"	
Power Type	Diesel	



Aspen Field Services

Job #: 26507 /

For more information, visit:

wellsfargo.com/equipmentseller

Inspection Details Cont'd	
Transmission Type	Powershift
Shift Type	Lever
Enclosed Cab	Yes
Engine MFR	Cummins
Controls	Lever
Hours	4416
Cab A-C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition
Keyless Ingnition	No
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Trelleborg: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	1 1/2"
Front Right Tire Depth Percentage	Above 50%
Front Right Tire Size	14.00-24
Front Left Tire Part Number	ContiTerminal: Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement Measurement	1 1/2"
Front Left Tire Depth Percentage	Above 50%
Front Left Tire Size	14.00-24
Back Right Tire Part Number	Continental: Not Available
Back Right Tire Condition	Gouge
Back Right Tire Tread Depth Measurement	1 1/2"
Back Right Tire Depth Percentage	Above 50%
Back Right Tire Size	14.00-24
Back Left Tire Part Number	Trelleborg: Not Available
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	1 1/2"
Back Left Tire Depth Percentage	Above 50%
Back Left Tire Size	Not Available
Mismatched Tires	Yes
Tilt Cylinders	No Leaks
Lift Cylinders	No Leaks
Mast Operation	Operational
Seat	Good Condition
Rear Lights	Good Condition
Working Lights	Good Condition

Inspection Details Cont'd		
Side Doors	Good Condition	
Side Glass Complete	Yes	
Mufflers	Good Condition	
ROPS Condition	Good Conditon	
Interior	Good Condition	
Hydraulic Couplers Present	No	
Hydraulic Couplers Visible Damage	No	
Engine Compartment	Dirty	
Roller Wear	No	
Side Shift Present	Yes	
Side Shift Operational	Operational	
Customer Decals Visible on Unit	No	
Comments	The seat is missing a head rest.	