



Item #15943684 - 2023 Tigercat 720G Wheel Feller Buncher



Item Details:

- Features: Rear View Camera, Joystick Steering, Requires Diesel Exhaust Fluid, Tigercat SW5702 56 in Feller Buncher
- Meter Reading: 3,285 Hours
- Serial # : 7207692
- Inspection Completed: 9/27/26

Shipping Details:

- Location Georgia (Atlanta area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	7207692	
CE Mark	No CE mark found	
Hour Meter / Odometer	3285 hrs	

v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		
v3 General Appearance # 4		
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders		

Glass		
Exterior Lights	Operational	
v3 General Appearance # 1		

Safety		
Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Inoperable	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Seats/Armrests		
Mirrors		

Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Auxiliary Hydraulic Control	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The gauge registers in the operating range.	
Warning Lights	Operational, Return oil filters bypassed light stays on	
Gauges	Operational	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Control Station #1		
Control Station #2		

Engine		
Item	Assessment	Photo
Engine	Requires Diesel Exhaust Fluid	
A/C Compressor	Operational	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		

DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	

Drivetrain		
Item	Assessment	Photo
Transmission	★★★★☆ Operational	
Transfer Case / Drop Box	★★★★☆ Operational	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★☆☆☆ Dripping leak	
Valves	★★★☆☆	
Hydraulic Tank	★★★☆☆	
Hoses (Hydraulics)	★★☆☆☆ Damaged hose.	
Auxiliary Hydraulic Plumbing	Operational	
Boom Lift Cylinder(s)	★★★☆☆	
Limited Function Check	The hydraulic system was operational.	

Excavator_2 # 1		
Excavator_2 # 2		
Excavator_2 # 3		
Excavator_2 # 4		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
v2 Chassis # 1		
v2 Chassis # 2		
v2 Chassis # 3		
v2 Chassis # 4		
v2 Chassis # 5		
Bunching Head Frame	★★★★☆	
Gathering Arms	★★★★☆	
Accumulator Arms	★★★★☆	

Tilt Cylinders	★★★★☆	
Arm Cylinders	★★★★☆	
Cutting Blade	★★★★☆	
Chassis #1		
Chassis #2		
Boom Condition	★★★★☆	
Boom Base Pin and Bushings	★★★★☆	

Bottom Covers		
Limited Function Check	The main components were operational in a limited check.	
Articulating Center Pins	★★★★☆	
Brake Type	Hydraulic	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Tire Brands	Firestone	
Left Front Tire		
Wheel Condition	★★★★☆	
Wheel Studs, Nuts, Lugs	★★★★☆	
Chassis #1		

Chassis #2		
------------	--	---

IronPlanet , Inc. © 2012 All Rights Reserved

2023 TIGERCAT 720G

UNIT: 7207692

Current Location: Wells Fargo (IMS), Atlanta, GA 30265, 555-555-5555



UNIT SPECS

Customer	Wells Fargo (IMS)
----------	-------------------

RECONDITIONING

Rear camera screen - inop	\$1,500	Hydraulic Pumps - Leak	\$5,500
Hydraulic Hose - Damaged	\$1,000	Horn - Inop	\$200
Return oil filters bypassed light on	\$750		
Total			\$8,950