

Aspen Field Services

Job #: 42716 / Serial #: 162956

For more information, visit: wellsfargo.com/equipmentseller









Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/ EqTJiabDe72trp6dr/full_report_0042716_EqTJiabDe72trp6dr.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	LeeBoy
Model	5300
Date of Inspection	06/08/2022
Location of Inspection	200 Altec Way, Mount Airy, NC, 27030, USA
VIN	162956
Hours/Odometer	196
EMS Panel	No Warnings
Transmission Type	Hydraulics
Dash	Good Condition
Switches	Good Condition
Steps	Good Condition
Outter Mirrors	NA Obstructed
Left Track Condition	Good Condition
Left Track Tread Measurement	43/32"





Aspen Field Services

Job #: 42716 / Serial #: 162956

For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd

Inspection Details Cont'd	
Right Track Condition	Poor Condition
Right Track Tread Measurement	43/32"
Engine Compartment	Good Condition
Oil Dipstick	The engine oil is dark in color
Coolant Reservoir	Good Condition
Rear Working Lights	Not Operational
Exhaust Pipe	Good Condition
Cylinders	Good Condition
Lift Cylinders	Good Condition
Hydraulic Hoses	Good Condition
Hydraulic Lines	Good Condition
Fuel Filter	Good Condition
Electric Fuel Pump	Good Condition
Beacon Lights	Not Operational
Hydraulic Housing	Good Condition
Bracket	Damaged
Front Right Roller	Damaged
Left Hopper Flashing	Missing
Intake Screen	Good Condition
Comments	The EMS Panel has no warnings on it, I was able to confirm with the site. The operators at the site are not very acquainted with the pavers, he was doing as much as he could to operate. The front lights are not operational as wells as the beacon lights. The front right roller and the bracket by the hopper is bent outwards. The front left of the hopper flashing has been pulled out of the holding bracket. There are gouges in the rubber on the right track. Both the right and left tracks are loose. The engine oil is dark in color.