



Buy this item and view more at www.truckplanet.com or call 800-211-3983

Item #12984395 - 2021 Hamm H10i Smooth Drum Compactor



Item Details:

- Features: Open Operator Station, 2021 US EPA Label, Deutz TCD3.6 L4 4 Cylinder 85 kW 3.6 L Diesel Engine, Requires Diesel Exhaust Fluid, Requires AdBlue, 84 in Drum
- Meter Reading: 1,232 Miles
- Serial # : WGH0H235CHAA02499
- Inspection Completed: 2/21/25

Shipping Details:

- Location Texas (Montgomery County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Hydraulics #10		
Pumps (Hydraulics)	★★★★	
Valves	★★★★	
Hydraulic Tank	★★★★	
Hoses	★★★★	

Drum Vibration Motors	★★★★☆	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	WGH0H235CHAA02499	
CE Mark	CE Marked	

Paint	Limestone residue, Damage	
Body Panels	No visible damage or missing components	
Steps	No visible damage or missing components.	
Hand Rails	No visible damage or missing components	
Exterior Lights	1 Inoperable / damaged / missing	
General Appearance #1		
General Appearance #2		

General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		

General Appearance #10		
General Appearance #11		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	
Safety #1		
Safety #2		

Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Mirrors		
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	
Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	

Warning Lights	Operational	
Gauges	Operational	
Hour Meter / Odometer	1232 mi	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		
Control Station #2		

Engine		
Item	Assessment	Photo
Emission Label		
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		
Engine #3		
Engine #4		

Engine #5		
Engine #6		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.


Item	Assessment	Photo
Right Front Drive Motor	★★★★☆	
Rear Center Drive Motor	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check - Compaction	The drivetrain was operational without a load.	
Drivetrain #1		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Chassis #1		

Compaction*

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Drum Condition	★★★★☆	
Rubber Drum Isolators	★★★★☆	
Drum Scraper	★★★★☆	
Frame Condition	★★★★☆	
Articulating Center Pins	★★★★☆	
Park Brake	★★★★☆	
Left Rear Tire	Size: 23.1-26 Brand: mitas Model: Ind uk10 Tread Depth: 20/32	

Right Rear Tire	Size: 23.1-26 Brand: mitas Model: Ind uk10 Tread Depth: 20/32	
Wheel Condition	No visible damage or missing components	
Limited Function Check (roller)	The main chassis components were operational.	
Compaction* #1		
Compaction* #2		
Compaction* #3		
Compaction* #4		

Compaction* #5		
Compaction* #6		
Compaction* #7		
Compaction* #8		
Compaction* #9		

Buy this item and view more at www.truckplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved