

Item #15936905 - 2024 Kobelco SK210LC Tracked Excavator



Item Details:

- Features: Control Pattern Changer, Tier 4, 9 ft 9 in Stick, 50 in Digging Bucket, Hydraulic Thumb
- Meter Reading: 1,978 Miles
- Serial # : YN17020516
- Inspection Completed: 9/17/26

Shipping Details:

- Location Tennessee (Nashville area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	YN17020516	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
Excavator* # 1		

Excavator* # 2		
Excavator* # 3		
Excavator* # 4		
Excavator* # 5		

Safety

Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	

Control Station

Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	The fault indicator shuts off after the engine oil pressure rises.	
Warning Lights	Operational, Check engine light stays on	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter / Odometer	1978 mi	
Air Conditioner	Operational	

Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Excavator* # 1		
Excavator* # 2		
Excavator* # 3		

Engine

Item	Assessment	Photo
Engine	No US EPA Label Present	
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Left Drive Motor	★★★★☆	
Right Drive Motor	★★★★☆	
Left Final Drive	★★★★☆	
Right Final Drive	★★★★☆	
Limited Function Check	The drivetrain was operational.	

Hydraulics

Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆ Low fluid level	
Hydraulic Control Pattern Changer	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Operational, End of stick	

Swing Motor	★★★★☆	
Hydraulic Center Swivel	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★★☆	
Bucket Cylinder	★★★★☆	
Thumb Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Excavator_2 # 1		

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Boom Condition	☆☆☆☆	 A yellow Kobelco excavator is shown from a side-rear perspective in a paved parking lot. The sky is blue with some clouds. An "IRON PLANET" watermark is visible in the bottom right corner of the photo.
Stick Condition	☆☆☆☆	 A close-up view of the yellow excavator's boom and stick, showing hydraulic hoses and mechanical components. The background shows a parking lot and a clear sky. An "IRON PLANET" watermark is visible in the bottom right corner.
Boom Base Pin and Bushings	☆☆☆☆	 A close-up view of the boom base pin and bushings, showing the yellow metal components and the hydraulic cylinder. An "IRON PLANET" watermark is visible in the bottom right corner.
Pin and Bushings Boom to Stick	☆☆☆☆	 A close-up view of the pin and bushings connecting the boom to the stick, showing the yellow metal components and the hydraulic cylinder. An "IRON PLANET" watermark is visible in the bottom right corner.
Pin and Bushings Stick to Bucket	☆☆☆☆	 A close-up view of the pin and bushings connecting the stick to the bucket, showing the yellow metal components and the hydraulic cylinder. An "IRON PLANET" watermark is visible in the bottom right corner.
Pins and Bushings Stick to Coupler	☆☆☆☆	 A close-up view of the pin and bushings connecting the stick to the coupler, showing the yellow metal components and the hydraulic cylinder. An "IRON PLANET" watermark is visible in the bottom right corner.

Turntable Bearing	★★★★☆	
Bottom Covers	★★★★☆	
Limited Function Check	The main components were operational in a limited check.	
Excavator* # 1		
Excavator* # 2		
Excavator* # 3		
Excavator* # 4		
Excavator* # 5		

Excavator* # 6		
Excavator* # 7		
Excavator* # 8		

Undercarriage

Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grousers) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.

Item	Assessment	Photo
Left Roller Frame	★★★★☆	
Left Track Tensioner	★★★★☆	
Left Track Pads	★★★★☆ 31 in Wide Triple Grouser	
Left Grouser Height	25 mm	
Left Track Links	106 mm	
Left Track Bushings	40 mm	

Left Carrier Rollers	2 carrier rollers #1 98 mm #2 98 mm	
Left Bottom Rollers	8 Bottom Rollers #1 131 mm #2 131 mm #3 131 mm #4 131 mm #5 131 mm #6 131 mm #7 131 mm #8 131 mm	
Left Idler	20 mm	
Left Sprocket	★★★★☆	
Right Roller Frame	★★★★☆	
Right Track Tensioner	★★★★☆	
Right Track Pads	★★★★☆ 31 in Wide Triple Grouser	

Right Grouser Height	26 mm	
Right Track Links	107 mm	
Right Track Bushings	39 mm	
Right Carrier Rollers	2 Carrier Rollers #1 108 mm #2 108 mm	
Right Bottom Rollers	8 Bottom Rollers: #1 130 mm #2 130 mm #3 130 mm #4 130 mm #5 130 mm #6 130 mm #7 130 mm #8 130 mm	
Right Idler	19 mm	
Right Sprocket	★★★★☆	

Specialty

Item	Assessment	Photo
Excavator Bucket Condition	★★☆☆☆ Coupler	
Bucket Cutting Edge/Shanks/Teeth	★★☆☆☆ No visible damage or missing components	
Thumb	★★☆☆☆ Hydraulic thumb	
Excavator_2 # 1		
Excavator_2 # 2		
Excavator_2 # 3		

Excavator_2 # 4		
Excavator_2 # 5		
Excavator_2 # 6		
Excavator_2 # 7		

2024 KOBELCO SK210LC-11

UNIT: YN17020516

Current Location: Wells Fargo (IMS), Lebanon, TN 37090, 555-555-5555



UNIT SPECS

Customer	Wells Fargo (IMS)
Year	2024
Make	Kobelco
Model	SK210LC-11
Unit Number	YN17020516

RECONDITIONING

Check engine light on	\$4,500	Hydraulic Fluid Level Low	\$350
Total			\$4,850