



Buy this item and view more at [www.truckplanet.com](http://www.truckplanet.com) or call 800-211-3983

## Item #15092789 - 2021 Hyundai 110D-9 25000 lb Forklift



### Item Details:

- Features: 2 Stage Mast, 197 in Max Lift Height, 162 in Lowered Mast Height, 52 in Forks, Side Shift, Fork Positioner, Solid Pneumatic Tires
- Meter Reading: 14,537 Hours
- Serial # : HHKHFT21PF0000303
- Inspection Completed: 4/15/26


### Shipping Details:

- Location Washington (Lewis County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

# Inspection Report



**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected







General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		







Serial Number / VIN	HHKHFT21PF0000303	
Paint	Damage	
Body Panels	No visible damage or missing components.	
Fenders	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
General Appearance #1		

General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		

General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		







<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	








<b>Control Station</b>		
Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Mirrors		
Glass	No visible damage or missing components	
Cab Doors	No visible damage or missing components	
Seat/Armrests	No visible damage or missing components	
Hydraulic Controls	★★★★☆	
Steering Control	★★★★☆ Heavy steering wheel play	







Drivetrain Controls	★★★★☆	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter	14537 hrs, Operational hour meter	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		
Control Station #2		







Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		
Control Station #7		
Control Station #8		
Control Station #9		

Control Station #10		
Control Station #11		

<b>Engine</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Emission Label		
A/C Compressor	In place; ambient temperature too cold to check operation	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	☆☆☆☆	
Oil Leaks	No dripping leaks	
Engine - Left Side		







Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran.	
Engine #1		
Engine #2		
Engine #3		
Engine #4		
Engine #5		



Engine #6		
Engine #7		
Engine #8		
Engine #9		
Engine #10		
Engine #11		








<b>Drivetrain</b>		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Transmission	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Final Drives	★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		




Drivetrain #4















<h2>Hydraulics</h2>		
<p>See photos for condition</p>		
Item	Assessment	Photo
Pumps (Hydraulics)	★ ★ ★ ☆	
Valves	★ ★ ★ ☆	
Hydraulic Tank	★ ★ ★ ☆	
Hoses (Hydraulics)	★ ★ ★ ☆	
Steering Cylinders	★ ★ ★ ☆	
Mast Lift Cylinders	★ ★ ★ ☆	








Mast Tilt Cylinders	★★★★☆	
Side Shift Cylinder	★★★★☆	
Fork Positioning Cylinder (on fork carriage)	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		

Hydraulics #5		
Hydraulics #6		
Hydraulics #7		
Hydraulics #8		
Hydraulics #9		
Hydraulics #10		
Hydraulics #11		

Hydraulics #12		
Hydraulics #13		
Hydraulics #14		

Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Mast/Boom Condition	★★☆☆ Heavy wear	
Chain / Tensioners	★★☆☆ Heavy wear	
Carriage Rollers and Guides	★★☆☆	
Load Back Rest	★★☆☆	
Side Shift	★★☆☆	
Forks	★★☆☆	

Steering Linkage	★★★★☆	
Frame Condition	★★★★☆	
Park Brake	★★★★☆ Held against power	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Left Front Tire	No visible defects	
Left Rear Tire	No visible defects	
Right Rear Tire	No visible defects	
Right Front Tire	No visible defects	

Tire Condition		
Wheel Condition	No visible damage or missing components	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		

Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		

**Buy this item and view more at [www.truckplanet.com](http://www.truckplanet.com) or call 800-211-3983**

IronPlanet, Inc. © 2012 All Rights Reserved