

## BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/16/2021 J5189521

INSPECTOR: 5932 INSPECTION ID 138047

VOLVO Year 2018 Make

Model	9700	VIN	3CET2V929J5189521
SPECIFICATION WORKSHEET			
Interior Options Interior Color:	BLACK	Steering Options Power Steering?:	Yes

Engine Options A	
Eng Make:	VOLVO
Eng Model:	D13
Eng Serial:	NA
Eng HP:	435
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	12'
Overall Width:	8'

Engine Options B	
Odometer:	156065
Hub odometer:	NA
ECU HP:	500
ECU Miles:	156073
Eng Hours:	NA

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	211

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	315
Rear Ratio:	2.64
F Axle (lbs):	16,500
R Axle (lbs):	10,800
GVWR (lbs):	49,400
Suspension:	AIR RIDE
Tag Axle Capacity:	22,100
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	3000/4000 5TH GEN
Trans Speed:	12

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and	any additional comments:



BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/16/2021 | J5189521 |

INSPECTOR: 5932 INSPECTION ID 138047

Brakes Options		Brakes				
ABS:	YES	Steer Axle Brakes:	50%	50%	(1)	
HYD:	NO	Drive Axle Brakes:	50%	50%	(2)	
AIR:	YES		50%	50%	(3)	
DISK:	YES				(4)	
DRUM:	NO				(5)	
Brake Plates:	FRONT N / REAR N				(6)	

Tires [Front]		Tires [Rear]	
Size:	315/80 R22.5	Size:	315/80 R22.5
Wheels:	ALUMINUM	Wheels:	ALUMINUM
Detail:		Detail:	
STEER	R AXLE DRIVE AXLE #1 DRIVE AXLE #2		Brake Legend

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		10 / 32nd LUG / R1	8 / 32nd LUG / R1
DIGUT	12 / 32nd HIGHWAY / V		
RIGHT	in in		
		9 / 32nd LUG / R1	/ 32nd /
FRONT -		10 / 32nd LUG / R1	/ 32nd /
	iiii		
LEFT	11 / 32nd HIGHWAY / V		
		9 / 32nd LUG / R1	7 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP

CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs.
REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend
H = HIGHWAY L = LUG



BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/16/2021 | J5189521

INSPECTOR: 5932 INSPECTION ID 138047

CONDITION REPORT

Engine Compartment Area		COMMENTS
Operational Test		COMMENTS
In Cab Inspection		COMMENTS
X Windshield, Door & Any Other Glass	RIGHT WINDS	SHIELD CHIP
Outside Inspection		COMMENTS
X Paint Condition & Physical Damage	BODY DAMAG	GE
Under Vehicle Inspection		COMMENTS
Tires/Wheels/Brakes		COMMENTS
X Tires/Wheels	6 BAD TIRES	

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------



#### **BUS**

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/16/2021 | J5189521 |

INSPECTOR: 5932 INSPECTION ID 138047

# RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Windshield, Door & Any Other Glass	X   RIGHT WINDSHIELD CHIP
Paint Condition & Physical Damage	X   BODY DAMAGE
Tires/Wheels	X   6 BAD TIRES
FRONTBUMPER	DAMAGED
FRONTPANEL	DAMAGED
RIGHT SIDE # 1 CARGO DOOR	DAMAGED
RIGHT SIDE # 2 CARGO DOOR	DAMAGED
RIGHT SIDE # 3 CARGO DOOR	DAMAGED
RIGHT SIDE PANEL	DAMAGED
RIGHT SIDE REAR WHEELHOUSE	DAMAGED
LEFT SIDE LOWER FRONT DOOR	DAMAGED
LEFT SIDE # 2 CARGO DOOR	DAMAGED
LEFT SIDE PANEL	DAMAGED
LEFT FRONT WHEELHOUSE	DAMAGED
ENGINE LID	DAMAGED
REAR CAP	DAMAGED
REAR BUMPER CENTER	DAMAGED
STONE GUARD	DAMAGED

#### COMMENTS:

THE COACH WAS INSPECTED AT THE CUSTOMER'S YARD. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE FRONT BUMPER, FRONT PANEL, RIGHT WINDSHIELD, RIGHT SIDE, LEFT SIDE, ENGINE LID AND REAR BUMPER. THERE WERE ALSO SIX BAD TIRES. THERE WERE TWO CUP HOLDERS AND TWENTY ONE OUTLETS WITH USB PORTS.



BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/16/2021 | J5189521

INSPECTOR: 5932 INSPECTION ID 138047




































#### BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER J5189521 03/16/2021

INSPECTOR: 5932 INSPECTION ID 138047





**FRONT** 



















**ENGINE COMPARTMENT RIGHT SIDE** 















BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
03/16/2021 | J5189521 |

INSPECTOR: 5932 INSPECTION ID 138047



































BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
03/16/2021 | J5189521 |

INSPECTOR: 5932 INSPECTION ID 138047









