## DEKRA

### DEKRA Services Inc.

### Customer Service 770-257-0107

CLIENT			
362 - Wells F	argo Equi	pment Mana	agement
INSP DATE		VIN (LAST 8)	
03/25/2021		HC713765	

2017 Make

H3-45 VIN

ALLISON

5B00

6

BUS

#### INSPECTOR: 5932 INSPECTION ID 138563

Yes

45'

149"

102"

58

PREVOST 2PCH33492HC713765

Year Model

SPECIFICATION WORKSHEET

Eng Model:

Eng Serial:

Trans Make:

Trans Model:

Trans Speed:

Eng HP: Cruise: Clean air idle:

Interior Options Interior Color:

Engine Options A Eng Make: 
 Steering Options

 BLUE
 Power Steering?:

	Overall Condition
VOLVO	Overall Length:
D13	Overall Height:
0131167671	Overall Width:
435	
Yes	
Yes	

Miscellaneous Seating Capacity:

Engine Options B	
Odometer:	316709
Hub odometer:	NA
ECU HP:	550
ECU Miles:	316724
Eng Hours:	NA

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	216

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	316
Rear Ratio:	2.50
F Axle (lbs):	16,500
R Axle (lbs):	14,000
GVWR (lbs):	53,000
Suspension:	AIR RIDE
Tag Axle Capacity:	22,500
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes
Transmission Options	

Electronic Engine Controls:	Ye
Full Gauge Package:	Ye
Wraparound Dash:	Ye
Power Mirrors:	Ye
Tilt / Telescopic Steering Wheel:	Ye
AirRide Driver's Seat:	Ye
Restroom:	Ye
PA System:	Ye
Audio - Video System:	Ye
Number of Video Monitors:	
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	No
Global Positioning System:	Ye
In Motion Satellite TV System:	N
Road Viewing Monitor System:	Ye
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Ye
Power Windshield Sun Visors:	Ye
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Ye
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Ye
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any additio NA	nal comments

DEK	(RA Servio	EKRA es Inc. vice 770-2		go Equipment N eet name   vin (last HC7137	8) PO NUMBER	INSPECTOR: 5932 INSPECTION ID 138563
Brakes (	Options			Brakes		
ABS:		YES		Drive Axle Brakes:		(1)
HYD:		NO				(2)
AIR:		YES				(3)
DISK: DRUM:		YES				(4)
DRUM: Brake P	lator:	NO ERON	T N / REAR N			(5)
		ПКОМ				
Tires [Fi Size:	ront]	315/80	B22.5	Tires [Rear] Size:	315/80 R2	2.5
Wheels:		ALUM		 Wheels:	ALUMINU	
Detail:		ALOIM		Detail:	ALOMINO	
	STEER AXLE 11 / 32nd HIGHWAY / V	DRIVE AXLE #1 9 / 32nd LUG / R1	DRIVE AXLE #2 9 / 32nd LUG / R1			Brake Legend BD = DRUM HAS MORE THAN 1/16 INCH LIF CL = CRACKED LINING LS = LEAKING SEAL(S)
RIGHT		6 / 32nd	/ 32nd			Tire Legend C = CUT D = DRY ROT F = FLAT M = MISMATCHED TIRES/CASING
FRONT		/ R1 2 / 32nd LUG / R1	/ / 32nd /			MA = MISMATCHED AXLES (FRONT vs. REAR) V = VIRGIN W = IRREGULAR WEAR R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIME
LEFT	11 / 32nd HIGHWAY / V					Tread Legend H = HIGHWAY L = LUG
		3 / 32nd LUG / R1	8 / 32nd LUG / R1			

DEKRA Services Inc. Customer Service 770-257-0107	BUS client 362 - Wells Fargo Equipment Management INSP DATE FLEET NAME VIN (LAST 8) PO NUMBER 03/25/2021 HC713765	INSPECTOR: 5932 INSPECTION ID 138563
CONDITION REPORT		
Engine Compartment Area	COMMENTS	
Operational Test	COMMENTS	
In Cab Inspection X Windshield, Door & Any Other Glass	COMMENTS RIGHT WINDSHIELD CHIP	

Х	X Interior Condition/ Seats, Panels, Etc. # 32 SEAT CL			GED	
X	Outside Inspection         COMMENTS           X         Paint Condition & Physical Damage         BODY DAMAGE				
	Under Vehicle Inspection COMMENTS				
Tires/Wheels/Brakes COMMENTS					
Х	X Tires/Wheels		6 BAD TIRES		
Additional Services Requested			Status	Comments	

# DEKRA

**DEKRA Services Inc.** 

#### CLIENT INSP DATE 03/25/2021 Customer Service 770-257-0107

BUS 362 - Wells Fargo Equipment Management FLEET NAME VIN (LAST 8) PO NUMBER HC713765

### RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Windshield, Door & Any Other Glass	X   RIGHT WINDSHIELD CHIP
Interior Condition/ Seats, Panels, Etc.	X   # 32 SEAT CUSHION DAMAGED
Paint Condition & Physical Damage	X   BODY DAMAGE
Tires/Wheels	X   6 BAD TIRES
LEFT SIDE # 2 DOOR	DAMAGE
LEFT SIDE # 4 DOOR	DAMAGE
LEFT SIDE # 5 DOOR	DAMAGE
RIGHT SIDE ENGINE DOOR	DAMAGE
REAR BUMPER	DAMAGE

COMMENTS: THE COACH WAS INSPECTED AT THE REPO YARD. THE UNIT WAS IN GOOD RUNNING CONDITION. THERE WAS DAMAGE TO THE RIGHT WINDSHIELD, LEFT SIDE DOORS, RIGHT SIDE ENGINE DOOR, REAR DUMPER AND PASSENGER SEAT CUSHION. THERE WERE ALSO SIX BAD TIRES. THERE NO PLUGS OR USB PORTS. THERE WERE TWO SMALL TABLES.



BUS CLIENT 362 - Wells Fargo Equipment Management INSP date | Fleet NAME | VIN (LAST 8) | PO NUMBER 03/25/2021 HC713765

INSPECTOR: 5932 INSPECTION ID 138563










### ENTRY WAY STEPS AT FRONT DOOR









INSIDE OF BUS, FRONT TO BACK



BUS CLIENT 362 - Wells Fargo Equipment Management INSP date | Fleet NAME | VIN (LAST 8) | PO NUMBER 03/25/2021 HC713765

INSPECTOR: 5932 INSPECTION ID 138563



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT



FRONT



**INSIDE RESTROOM #1** 









BUS CLIENT 362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 03/25/2021 | HC713765 | INSPECTOR: 5932 INSPECTION ID 138563



