

2019 Wacker Neuson WL60 Wheel Loader

ITEM#

8737954

LOCATION

Jonesboro, Arkansas, United States, 72401



(89 - photos & videos)

Print

Add to Watch List

ITEM DETAILS

METER READING

1,198 Hours

SERIAL #

3055031

Enclosed Cab, Air Conditioner, Air Ride Seat, 2019 US EPA Label, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 3 cyd 84 in Bucket, Forks

Financing







Inspection Report

Important Information

INSPECTION REPORT

Please note that as the buyer, you are responsible for reviewing the entire inspection report when evaluating an item.

GENERAL APPEARANCE













DESCRIPTION	RATING	DETAILS
Serial Number / VIN		3055031 
Paint		Heavy Rust And Corrosion 
Body Panels		No visible damage or missing components.
Fenders		No visible damage or missing components. 
Steps		No visible damage or missing components. 
Hand Rails		No visible damage or missing components 
Exterior Lights		All lights operational 



SAFETY












DESCRIPTION	RATING	DETAILS
Travel Alarm		Operational
Horn		Operational
Seat Belts		Operational
Current Safety Manual		No
Current Operator/Maintenance Manual		No

CONTROL STATION

DESCRIPTION	RATING	DETAILS
Seat/Armrests		No visible damage or missing components 
Glass		No visible damage or missing components 
Mirrors		
Cab Doors		No visible damage or missing components 
Steering Controls		
Hydraulic Controls		
Drivetrain Controls		
Dash Console		
Engine Oil Pressure		No oil pressure indicator
Warning Lights		Operational
Gauges		Operational 
Hour Meter (pre-inspection)		1198.9 hrs 
Hour Meter		1198 hrs - No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed. 
Air Conditioner		Operational
Heater		Operational
Limited Function Check		The main components are in place and operational as noted. 







ENGINE

DESCRIPTION	RATING	DETAILS
Engine		2019 US EPA Label, Requires Diesel Exhaust Fluid
Emission Label		
A/C Compressor		Operational 
Blow-by (subjective visual observation)		No noticeable vapor or pressure
Starter		Operational
Exhaust System		No visible damage or missing components 
Radiator		
Oil Leaks		No dripping leaks 
Fuel Leaks		No dripping leaks 
Cooling System Leaks		No dripping leaks 
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check		The engine started and ran. 










DRIVETRAIN

DESCRIPTION	RATING	DETAILS
Transmission		
Drive/Propel Motors		
Transfer Case / Drop Box		Operational 
Front Drive Axle		
Rear Drive Axle		
Final Drives		
Limited Function Check		The drivetrain was operational.



HYDRAULICS














See photos for condition

DESCRIPTION	RATING	DETAILS
Pumps (Hydraulics)		
Valves		
Hydraulic Tank		
Hoses (Hydraulics)		
Loader Lift Cylinders		
Bucket Tilt Cylinders		
Auxiliary Hydraulic Plumbing		Not operationally checked, Front 
Steering Cylinders		
Limited Function Check		The hydraulic system was operational.



CHASSIS

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.





DESCRIPTION	RATING	DETAILS
Articulating Center Pins		
Brake Type		Hydraulic
Master Cylinder		
Brake Lines/Hoses		Not operationally checked
Park Brake		
Limited Function Check - Brakes		The brake system functioned, stopping and holding the machine.
Frame Condition		
Left Front Tire		Mitas 405/70 r 18 47 /32" Tread Depth 
Left Rear Tire		44 /32" Tread Depth 
Right Rear Tire		43 /32" Tread Depth 
Right Front Tire		50 /32" Tread Depth 
Wheel Condition		No visible damage or missing components 
Lift Arm Condition		
Chassis to Arm Pins		
Tilt Linkage		
Tilt Linkage Pins and Bushings		
Bucket to Arm Pins		
Quick Coupler to Arms Pins		
Limited Function Check		The main chassis components were operational in a limited check.



SPECIALTY

DESCRIPTION	RATING	DETAILS
 (4)		

WHEEL LOADER*

DESCRIPTION	RATING	DETAILS
Loader Bucket Condition		
Loader Bucket Cutting Edge		No visible damage or missing components 
Loader Quick Coupler		Not operationally checked 
Forks		



NON-DISPUTABLE

Recommendations For You Search all