



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/xQcysQLwik5CDYKfB/full_report_0029748_xQcysQLwik5CDYKfB.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2018
Make	Kalmar Ottawa
Model	T2 4x2
VIN	348176
Type	4x2 Off Road Yard Dog
Inspection Date	4/26/2021
Location of Business	JJ Kane Auctioneers - Ft Wayne; 3020 Commercial Rd, Fort Wayne, IN 46809
Odometer	10041
Hours	NA
Enclosed Cab	Yes
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition
GVWR	Not Available



Aspen Field Services

Job #: 29748 /

Serial #: 348176

For more information, visit:

wellsfargo.com/equipmentseller

OTTAWA T2 4X2 OFF ROAD YARD TRACTOR

Inspection Details Cont'd	
Drivers Seat	Good Condition
Hi Back Seats	No
Interior	Good Condition
Engine Compartment	Good Condition
Engine Make	Not Available
Engine Serial Number	Not Available
Stack Exhaust	Good Condition
Cab Steps	Good Condition
Cab Door	Good Condition
Operational Test	Operational
Front Left Tire Condition	Good Condition
Front Left Tire Brand	Goodyear
Front Left Tire Size	Not Visible
Front Left Tire Tread Depth	16/32"
Front Right Tire Condition	Fair Condition
Front Right Tire Brand	Goodyear
Front Right Tire Size	11R22.5
Front Right Tire Tread Depth	7/32"
Outer Back Left Tire Condition	Good Condition
Outer Back Left Tire Brand	Falken
Outer Back Left Tire Size	Not Visible
Outer Back Left Tire Tread Depth	14/32"
Inner Back Left Tire Condition	Good Condition
Inner Back Left Tire Tread Depth	14/32"
Outer Back Right Tire Condition	Good Condition
Outer Back Right Tire Brand	Michelin
Outer Back Right Tire Size	11R22.5
Outer Back Right Tire Tread Depth	14/32"
Inner Back Right Tire Condition	Good Condition
Inner Back Right Tire Tread Depth	15/32"
Mismatched Tires	Yes
Front Axle Suspension	Leaf - Good Condition
Rear Axle Suspension	None - Solid Mount
Fifth Wheel	Poor Condition - Needs to be Replaced
Platform	Good Condition
Body Paint	Good Condition
Exterior Color	White
Interior Color	Gray
Headlights	Operational
Tailgate Lights	Operational

Inspection Details Cont'd	
Horn	Not Operational
Fenders	Damaged
Back Up Alarm	Operational
Comments	The unit is in overall fair condition. The interior is in good condition with minimal wear and tear. The fifth wheel top plate is worn out and needs to be replaced. The rear fenders are damaged. The horn is not operational. The engine starts and runs smoothly and there are no visible signs of leaks.