



Item #5657204 - RBR Vector 300 Fertilizer Spreader



Item Details:

- Features: 2016 US EPA Label, Cummins 6 Cylinder 305 hp 8.3 L Diesel Engine,
- Meter Reading: 2,576 Hours
- Serial # : M1700633
- Inspection Completed: 11/19/21

Shipping Details:

- Location Mississippi (Marshall County)
- Loading Dock Available: No

Inspection Report


Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	M1700633	
Hour Meter / Odometer	2576.4 hrs, Not operationally checked	
v2 General Appearance # 1		
v2 General Appearance # 2		
v2 General Appearance # 3		
v2 General Appearance # 4		
v2 General Appearance # 5		

v2 General Appearance # 6		
v2 General Appearance # 7		
v2 General Appearance # 8		
v2 General Appearance # 9		
v2 General Appearance # 10		
v2 General Appearance # 11		
v2 General Appearance # 12		

v2 General Appearance # 13		
v2 General Appearance # 14		
v2 General Appearance # 15		
v2 General Appearance # 16		
v2 General Appearance # 17		
v2 General Appearance # 18		
v2 General Appearance # 19		

v2 General Appearance # 20		
v2 General Appearance # 21		
v2 General Appearance # 22		
v2 General Appearance # 23		
v2 General Appearance # 24		
v2 General Appearance # 25		
v2 General Appearance # 26		

v2 General Appearance # 27		
v2 General Appearance # 28		
v2 General Appearance # 29		
v2 General Appearance # 30		
v2 General Appearance # 31		
v2 General Appearance # 32		
v2 General Appearance # 33		

v2 General Appearance # 34		
v2 General Appearance # 35		
v2 General Appearance # 36		
v2 General Appearance # 37		

Engine		
Item	Assessment	Photo
Engine #1		
Engine #2		
Engine #3		
Engine #4		
Engine #5		
Engine #6		

Engine #7



Limited Function Check

Engine	The engine would crank with a jump but would not run.
Drivetrain	The drivetrain could not be operationally checked.
Hydraulics	The hydraulic system could not be operationally checked.

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved