

2021 New Holland C332

Unit: JAF0C332TMM495185



Download Reconditioning Printout

UNIT SPECS

Customer Wells Fargo (MS)

LOCATION

WELLS FARGO (MS)
6050 AZLE AVENUE
LAKE WORTH, TX 76135

VIEW ALL PHOTOS

FULL SPECS

RECONDITIONING

Chassis

Frame Condition	Rating: Good	
Lift Arm Condition	Rating: Good	
Chassis To Arm Pins		
Little movement		
Quick Coupler To Arms Pins		
Little movement		
Limited Function Check (Chassis)		
The main chassis components were operational in a limited check.		

Control Station

Seat/Armrests		
No visible damage or missing components		
Glass		
No visible damage or missing components		
Steering Controls		
Operational		
Hydraulic Controls		
Operational		
Auxiliary Hydraulic Control		
Not operationally checked		
Drivetrain Controls		
Operational		
Dash Console		
	Rating: Good	
Engine Oil Pressure		
The fault indicator shuts off after the engine oil pressure rises.		
Warning Lights		
Operational		
Gauges		
Operational		
Rear View Camera		
Display inoperable		
Hour Meter (Pre-inspection)		
546.5 hrs		
Hour Meter		
546 hrs		
Limited Function Check (Control Station)		
The main components are in place and operational as noted.		
Control Station		
Enclosed Cab (Door missing), Air Conditioner		

Drivetrain

Drive Motors		
Operational		
Final Drives		
	Rating: Good	
Limited Function Check (Drivetrain)		
The drivetrain was operational.		

Engine

Blow-by (Subjective Visual Observation)		
Recirculating system		
Starter		
Operational		
Exhaust System		
No visible damage or missing components		
Radiator		
No visible leaks		
Oil Leaks		
No visible leaks		
Fuel Leaks		
No visible leaks		
Cooling System Leaks		
No visible leaks		
Limited Function Check (Engine)		
The engine started and ran.		

General Appearance

Year	2021	
Make	New Holland	
Model	C332	
Serial Number / VIN	JAF0C332TMM495185	
Pre-Operational Checks	Confirm Fluids Checked: Engine Coolant, Confirm Fluids Checked: Engine(s) Oil, Confirm Fluids Checked: Fuel Level	
Paint	No visible damage	
Body Panels	No visible damage or missing components	
Cab/Canopy Overhead Structural Framework	No visible damage	
Steps	No visible damage or missing components	
Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	

Hydraulics

Pumps (Hydraulics)	Operational	
Valves	Operational	
Hydraulic Tank	No visible leaks	
Hoses (Hydraulics)		Rating: Good
Auxiliary Hydraulic Plumbing	Not operationally checked	
Loader Lift Cylinders		Rating: Good
Bucket Tilt Cylinders		Rating: Good
Limited Function Check (Hydraulics)	The hydraulic system was operational.	

Logistics Information

Shipping Dimensions	13 ft Long x 6 ft 6 in Wide x 7 ft Tall 0.0 lb Shipping Weight	
General Shipping Information	Yes: Does this Unit Run? Yes: Is self propelled, does the unit travel? Yes: Inflated Tires - Item can roll? No: Is the unit taller than 12'? No: Is the unit wider than 8'6"? No: Noticeable fluid leaks?	
Road Related Shipping Info	Yes: Lights Operate? Yes: Brakes Operate? Yes: Tires OK?	

Safety

Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	

Specialty

Quick Coupler	Not operationally checked	
Loader Bucket Condition		Rating: Good
Loader Bucket Cutting Edge/Shanks/Teeth		Rating: Good
Front Attachment	Front Attachment Details, Quick Coupler Type: Hydraulic Coupler, Bucket Type: Bucket	

Rubber Track Undercarriage

Roller Frames		Rating: Good
Track Belt Condition	No visible damage	
Rubber Belt Drive Lugs	No visible damage	
Track Tensioners	Operational	