



# Aspen Field Services

Job #: 28468 /

Serial #: H2350108

For more information, visit:

[wellsfargo.com/equipseller](https://wellsfargo.com/equipseller)

## HAMM H 10I ROLLER



### Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.staging.aspenfieldservices.com/api/attachments/get/5oBJ9ribX3mfZd7iZ/full\\_report\\_0028468\\_5oBJ9ribX3mfZd7iZ.pdf?view](https://app.staging.aspenfieldservices.com/api/attachments/get/5oBJ9ribX3mfZd7iZ/full_report_0028468_5oBJ9ribX3mfZd7iZ.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Hamm
Model	H 10i
Serial Number	H2350108
Type	Roller
Date Of Inspection	3/9/2021
Location of Business	JJ Kane Auctioneers- 100 Liberty Rd, Villa Rica, GA 30180
Attachment(s)/ Accessory(s)	Roller Serial Number Not Visible and Roller Serial Number Not Visible
Enclosed Cab	No
Engine MFR	Deutz
Engine Serial Number	11962807
Hours	1002
Active Warnings	None
Cab A-C	No
Cab A-C Condition	N/A



# Aspen Field Services

Job #: 28468 /

Serial #: H2350108

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

HAMM H 10I ROLLER

Inspection Details Cont'd	
Cab Heat	No
Cab Heat Condition	N/A
Backup Camera	No
Keyless Start	No
Visual Inspection	Clean
Operational Test	Operational
Back Right Tire Brand	Hamm
Back Right Tire Condition	Good Condition
Back Right Tire Size	23.1-26
Back Right Tire Tread Depth Measurement	1"
Back Right Tire Depth Percentage	Above 50%
Back Left Tire Brand	Hamm
Back Left Tire Condition	Good Condition
Back Left Tire Size	23.1-26
Back Left Tire Tread Depth Measurement	1"
Back Left Tire Depth Percentage	Above 50%
Mismatched Tires	No
Seat	Good Condition
Controls	Standard
Front Door	N/A
Side Glass Complete	N/A
Steps	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Door	Does not open
Engine Compartment	Not Accessible
Interior	Good Condition
Customer Decals Visible on Unit	No
Headlights	Non Operational
Tailgate Lights	Good Condition
Left Articulation Cylinder	Good Condition
Right Articulation Cylinder	Good Condition
Hydraulic Lines	Good Condition - No Leaks
Roller Thickness	1"
Roller Diameter	52"
Roller Width	88"
Comments	The working lights are non operational. The site contact was unable to open up the engine door during the time of inspection.

## Inspection Details Cont'd