



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #14978244 - 2023 John Deere 544 P-Tier Wheel Loader



Item Details:

- Meter Reading: 1,826 Hours
- Serial # : 1DW544PAHPLZ17190
- Inspection Completed: 3/18/26

Shipping Details:

- Location Texas (Harris County)
- Pickup Hours: null-null







NOTE: This item is offered as-is, where-is with no IronClad Assurance, and a buyer may not dispute the condition of the item. IronPlanet claims no responsibility for the condition or description of this item. This item does not include any protection offered by IronClad Assurance. A buyer may NOT submit a dispute claim on this item.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.







Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Find it in Yard		
Item	Assessment	Photo
Assigned Lane and Spot	Located in Lane 7 Spot 7	





General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	1DW544PAHPLZ17190	
CE Mark	No CE mark found	
Hour Meter / Odometer	1826 hrs	

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		
Control Station #4		
Control Station #5		
Control Station #6		


Control Station #7		
Control Station #8		
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Engine	No US EPA Label Present Requires Diesel Exhaust Fluid	
v2 Engine # 1		
v2 Engine # 2		
v2 Engine # 3		
v2 Engine # 4		
v2 Engine # 5		
v2 Engine # 6		

v2 Engine # 7		
Limited Function Check	The engine started and ran.	

Drivetrain		
Item	Assessment	Photo
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		
Drivetrain #4		







Brakes		
Item	Assessment	Photo
Brakes	The brakes are operational.	

Hydraulics		
Item	Assessment	Photo
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Specialty		
Item	Assessment	Photo
Specialty #1		
Specialty #2		
Specialty #3		
Specialty #4		
Specialty #5		
Specialty #6		

Specialty #7



Chassis		
Item	Assessment	Photo
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		

Chassis #7		
Chassis #8		
Chassis #9		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved