

BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501

Information			
Complete VIN:	2PCG33498GC736042	Request ID:	2015260613
Unit number:		Year:	2016
Make:	PREVOST	Model:	X3-45

Vehicle location			
Customer:	YARD MGR	ZIP CODE:	91752
District:		City:	MIRA LOMA
State:	CA	Address:	3384 DE FOREST CIRCLE,
Phone:	951360-2550/800-4	Location:	Prevost Car Inc - Mira Loma, CA

Inspection Request

Inspection Instructions



Eng HP:

Cruise:

Clean air idle:

### DEKRA Services Inc. Customer Service 770-257-0107

### **BUS**

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501

Year	2016 Make	PREVOST
Model	X3-45 VIN	2PCG33498GC736042

SPECIFICATION WORKSHEET			
Interior Options Interior Color:	BLUE	Steering Options Power Steering?:	Yes
Engine Options A		Overall Condition	
Eng Make:	VOLVO	Overall Length:	45'
Eng Model:	D13J435P	Overall Height:	146"
Eng Serial:	1134961	Overall Width:	102"

425

Yes

Engine Options B	
Odometer:	230147
Hub odometer:	NA
ECU HP:	500
ECU Miles:	230158
Eng Hours:	NA

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	182

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	316
Rear Ratio:	4.25
F Axle (lbs):	16,500
R Axle (lbs):	14,000
GVWR (lbs):	53,000
Suspension:	AIR RIDE
Tag Axle Capacity:	22,500
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	No
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	B500
Trans Speed:	12

Seating Capacity:	55
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No.
Global Positioning System:	Yes
- · · · · · · · · · · · · · · · · · · ·	No.
In Motion Satellite TV System:	
Road Viewing Monitor System:	Yes
Wheelchair Lift:	Yes
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA



**Brakes Options** 

HYD:

AIR:

DISK:

DRUM:

Brake Plates:

# DEKRA Services Inc. Customer Service 770-257-0107

YES

NO

YES

YES

NO

FRONT N / REAR N

**BUS** 

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501

Brakes			
Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	70%	70%	(2)
	70%	70%	(3)
			(4)
			(5)
			(6)

Tires [Front]		Tires [Rear]	
Size:	315/80 R22.5	Size:	315/80 R22.5
Wheels:	ALUMINUM	Wheels:	ALUMINUM
Detail:		Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		10 / 32nd LUG / R1	8 / 32nd LUG / R1
RIGHT	14 / 32nd HIGHWAY / V		
FRONT		9 / 32nd LUG / R1	/ 32nd /
		8 / 32nd LUG / R1	/ 32nd /
LEFT			
	10 / 32nd HIGHWAY / V		
		9 / 32nd LUG / R1	13 / 32nd LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP CL = CRACKED LINING LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT M = MISMATCHED TIRES/CASING MA = MISMATCHED AXLES (FRONT vs. REAR)

V = VIRGIN W = IRREGULAR WEAR R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



ОК

Brakes

# DEKRA Services Inc. Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501

CONDITION REPORT **Engine Compartment Area** COMMENTS Fan Assembly, Shroud & Radiator Hose Condition ОК **Record Coolant Protection Level** ОК Oil in Cooling System ОК Coolant DCA Level **Coolant Level** Power/Manual Steering Fluid Level OK ОК Clutch Master Cylinder Fluid Level Brake Fluid Level ОК ОК Engine Oil Level ОК Oil, Coolant and Other Fluid Leaks ΟK Belt, Alignment, Condition & Adjustment Belt & Engine Driven Components ОК Exhaust & Intake Systems ОК ОК Visible Inspection of Starter N/A Other COMMENTS Operational Test ОК Batteries - Capable of Starting Engine ΟK Starter Condition ОК Steering Free Play ОК Clutch & Clutch Brake ОК Transmission Shifts ОК Brakes & Parking Brakes ΟK Throttle ОК Engine Brake ОК Air Pressure Build Up ОК Governed Air Pressure (psi) ОК Low Air Warning ОК Gauges ОК **Engine Warning System** ΟK Seat Belts ОК HVAC System ОК Record A/C Temperature ОК Windshield Wipers & Washers ΟK Door Locks & Latches ОК Window Operation Other N/A In Cab Inspection COMMENTS LEFT WINDSHIELD DAMAGED Windshield, Door & Any Other Glass ОК Interior Condition/ Seats, Panels, Etc. ОК DOT Required Safety Equipment N/A Other Outside Inspection COMMENTS Paint Condition & Physical Damage OK ОК Lights and Reflectors ОК ОК Fuel Tank Mounting & Condition Batteries & Battery Box Intake & Exhaust Mounting & Condition OK N/A Under Vehicle Inspection COMMENTS ОК Kingpins/Steering Components Engine/Transmission Mounts ОК ОК Frame, Crossmemebers, Fasteners N/A Cab Mounts Driveshafts, U-joints, Yokes OK ОК Hydraulic Brake Lines & Components ОК Brake Hoses for Chafing & Cracking ОК Air Brake Components Transmission & Differential Fluid Levels ОК ΟK Transmission & Differential Leaks ОК Suspension Condition ОК N/A Other Tires/Wheels/Brakes COMMENTS ОК Tires/Wheels

Additional Services Requested Status Comments



#### BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE FLEET NAME VIN (LAST 8) PO NUMBER 09/23/2020 GC736042

INSPECTOR: 5932 INSPECTION ID 126501

# RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS	
Windshield, Door & Any Other Glass	X   LEFT WINDSHIELD DAMAGED	
FRONTBUMPER	DAMAGED	
ENGINE LID	DAMAGED	

COMMENTS:
THE BUST WAS INSPECTED AT PREVOST. THE UNIT WAS IN GOOD RUNNING CONDITION IN THE SERVICE DEPARTMENT. THE BUS WAS BEING SERVICED AT THE TIME OF THE INSPECTION. THERE WAS DAMAGE TO THE FRONT BUMPER, LEFT WINDSHIELD AND THE ENGINE LID.



## BUS

CLIENT

362 - Wells Fargo Equipment Management
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501



































BUS

CLIENT

362 - Wells Fargo Equipment Management INSP DATE FLEET NAME VIN (LAST 8) PO NUMBER 09/23/2020 GC736042

INSPECTOR: 5932 INSPECTION ID 126501



BACK



INSIDE OF BUS, BACK TO **FRONT** 



FLOOR OF BUS, BACK TO **FRONT** 

















ENGINE COMPARTMENT **RIGHT SIDE** 



**ENGINE COMPARTMENT LEFT** SIDE











**ADDITIONAL 4** 



**BUS** 

CLIENT

362 - Wells Fargo Equipment Management INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER 09/23/2020 | GC736042

INSPECTOR: 5932 INSPECTION ID 126501















