

Interior Options Interior Color:

# **DEKRA Services Inc. Customer Service 770-257-0107**

# BUS

INSPECTOR: 5932 INSPECTION ID 134037

INSP DATE VIN (LAST 8) PO NUMBER 12/14/2020 H2041507

Year	2017 Make	VAN HOOL
Model	TX45 VIN	YE2YC82BXH2041507

Steering Options
Power Steering?:

rear	2017	Wake	VAN HOOL
Model	TX45	VIN	YE2YC82BXH2041507
SPECIFICATION WORKSHEET			

BLUE

Engine Options A	
Eng Make:	CUMMINS
Eng Model:	ISX
Eng Serial:	75055499
Eng HP:	450
Cruise:	Yes
Clean air idle:	Yes

Overall Condition	
Overall Length:	45'
Overall Height:	12'
Overall Width:	102"

Engine Options B	
Odometer:	180435
Hub odometer:	NA
ECU HP:	500
ECU Miles:	179517
Eng Hours:	6961

Engine Options C	
Eng Brake:	JAKE
Fuel:	DIESEL
FT1 Capac (Gal):	216

Exterior Options A	
Air Horns:	NONE
Mirrors:	DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	2.4161
WheelBase (In):	24'6"
Rear Ratio:	3.42
F Axle (lbs):	17,600
R Axle (lbs):	17,600
GVWR (lbs):	54,000
Suspension:	AIR RIDE
Tag Axle Capacity:	27,500
Rear Axle Model:	NA
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	3000/4000 5TH GEN
Trans Speed:	6

Miscellaneous	
Seating Capacity:	57
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	Yes
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	4
Multi-Disc CD Changer:	Yes
Individual multi-Channel Audio System:	No
Global Positioning System:	Yes
In Motion Satellite TV System:	No
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	Yes
Other:	NA
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	GOOD
If Unit is not driveable or will not start, Explain:	NA
Any extra options or features not listed on front page and any ad	ditional comments:



INSPECTOR: 5932
INSPECTION ID
134037

## DEKRA Services Inc. Customer Service 770-257-0107

Brakes Options		
ABS:	YES	
HYD:	NO	
AIR:	YES	
DISK:	YES	
DRUM:	NO	
Brake Plates:	FRONT N / REAR N	

Brakes			
Steer Axle Brakes:	60%	60%	(1)
Drive Axle Brakes:	60%	60%	(2)
	60%	60%	(3)
			(4)
			(5)
			(6)

Tires [Front]		
Size:	315/80 R22.5	
Wheels:	ALUMINUM	
Detail:		

Tires [Rear]		
Size:	315/80 R22.5	
Wheels:	ALUMINUM	
Detail:		

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		11 / 32nd	14 / 32nd
	10 / 32nd	LUG / R1	LUG / R1
RIGHT	HIGHWAY / V	118	188
	1111		
		10 / 32nd	/ 32nd
FRONT		LUG / R1	/
		8 / 32nd	/ 32nd
		LUG / R1	/
LEFT			
	16 / 32nd		
	HIGHWAY / V		
		11 / 32nd	3 / 32nd
		LUG / R1	LUG / R1

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP CL = CRACKED LINING LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT M = MISMATCHED TIRES/CASING MA = MISMATCHED AXLES (FRONT vs. REAR)

V = VIRGIN W = IRREGULAR WEAR

R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



INSPECTOR: 5932 INSPECTION ID 134037

DEKRA Services Inc. Customer Service 770-257-0107

CONDITION REPORT

	Engine Compartment Area		COMMENTS		
	Operational Test		COMMENTS	COMMENTS	
	In Cab Inspection		COMMENTS	COMMENTS	
	Outside Inspection		COMMENTS	COMMENTS	
X	Paint Condition & Physical Damag	je BODY D	AMAGE		
	Under Vehicle Inspection		COMMENTS	COMMENTS	
X	Tires/Wheels/Brakes X Tires/Wheels 2 tires be		COMMENTS elow 10/32		
Additi	onal Services	Requested	Status	Comments	



INSPECTOR: 5932 INSPECTION ID 134037

INSP DATE | VIN (LAST 8) | PO NUMBER 12/14/2020 | H2041507

DEKRA Services Inc.
Customer Service 770-257-0107

# RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Paint Condition & Physical Damage	X   BODY DAMAGE
Tires/W heels	X   2 tires below 10/32
RIGHT SIDE # 3 CARGO DOOR	DAMAGED
RIGHT SIDE REAR WHEELHOUSE	DAMAGED
LEFT SIDE # 1 CARGO DOOR	DAMAGED
LEFT SIDE # 2 CARGO DOOR	DAMAGED
LEFT SIDE VENT DOOR	DAMAGED
LEFT TAIL LAMP	DAMAGED

#### COMMENTS

THE BUS WAS INSPECTED AT TCS IN THE CITY OF ORANGE. THE UNIT WAS N GOOR RUNNING CONDITION. THERE WAS DAMAGE TO THE RIGHT AND LEFT SIDE CARGO DOORS, REAR WHEELHOUSE



INSPECTOR: 5932 INSPECTION ID 134037

INSP DATE VIN (LAST 8) PO NUMBER 12/14/2020 H2041507



































INSP DATE | VIN (LAST 8) | PO NUMBER 12/14/2020 | H2041507

INSPECTOR: 5932
INSPECTION ID
134037



BACK



**FRONT** 



**FRONT** 















RIGHT SIDE















VIN (LAST 8) PO NUMBER

INSPECTOR: 5932
INSPECTION ID
134037

12/14/2020 H2041507 PO NUMBE



































**DEKRA Services Inc. Customer Service 770-257-0107**  **BUS** 

INSP DATE

VIN (LAST 8) PO NUMBER 12/14/2020 | H2041507

INSPECTOR: 5932 INSPECTION ID 134037





