

Qty	Product	Description	SLM	Unit Price	Net Amount
NT101	TOWLIFT INTERNAL DISCOUNT CLEVELAND				
	Segment: 1	SHUTTLE WAGON INSPECTION			Rental Maintenance
		Caution this segment will be invoiced to Towlift Internal Discount Cleveland 1-Insite will NOT talk to unit			
		2-no codes found for trans or eng using onboard diagnostics			
		3-rear coupler mirror NR			
		4-upper radiator hose wet			
		5-fan blade damaged (suggest checking mounts)			
		6-rear wiper switch seized			
		7-cup holder NR			
		8-right side mirror NR			
		9-front coupler center bolt falling out			
		10-tires need air			
		11-rear tires worn more than front			
		12-R FR sander hose NR			
		13-LR FR sander hose and bracket NR			
		14-LF Rear sander hose NR			
		15-sanders need cleaned out			
		16-air leak (valve right side by trans			
		17-brake reservoir Empty			
		18-both hyd manifolds leak			
		19-hyd pump leaks bad			
		20-trans filter wet by gasket			
		21-right rear rail scraper bent and twisted			
		22-slight play in u-joints			