DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

Year, Make:	2023 KENWORTH
Model:	T680
Full VIN:	1NKYD39X3PJ248237
Engine:	CUMMINS ISX12N
HP:	400 (RATED) 500 (ECU HP)
Clean air idle:	N/A
Sleeper (Size in):	INTEGRAL RAISED (76")
Wheelbase:	230
Mileage:	11647 (ODOM) NA (ECU MILES) NA (HUB ODOM)
Trans Make | Model:	| NA
Trans Type:	AUTOMATIC 12 SPD.
Suspension:	AIR RIDE
Front Axle:	SPICER/DANA @ 14,320
Front Axle Pos:	SET BACK
Rear Axle:	SPICER/DANA @ 40,000
Axle Type / Ratio:	TANDEM AXLE / 3.55 (RATIO)
3rd Axle:	NONE
GVW:	54,320
Power Steering:	Yes
Power Windows:	Dual
Air Cond:	Yes
Cruise Control:	Yes
Fuel Type:	LP GAS
Fuel Tanks / Material / Capacity:	2 / ALUMINUM / (1) (2) (3) (4)
Chassis Fairings:	FULL
Roof Fairings:	Yes Visor: NONE
Side Extenders:	Yes
Body Type | Cab Type:	Truck | CONVENTIONAL
Fifth Wheel:	AIR SLIDE
Tire Size (F) | Tire Size (R):	275/80 R22.5 | 275/80 R22.5
Steer Tire | Drive Tire Detail:	|
Cluster Test:	Yes \ Pass

Frame:	STEEL
Interior Type / Level:	STANDARD / HIGH
Upholstery:	CLOTH & VINYL
Refrigerator:	No
Seat Suspension (High Back):	DUAL AIR (DUAL)
Bumper:	AERO
Air Horns:	SINGLE
New Paint |Interior Color |Paint Color:	No | GREY | WHITE
Identification:	NONE
Exhaust (Finish):	SINGLE VERTICAL (STAINLESS)
Air Cleaners	INTERNAL
Front Wheels | Rear Wheels:	ALUMINUM | ALUMINUM
Radio:	AM/FM CD
PTO:	No
Mirrors:	DUAL POWER
Wet Line Kit:	No
Brake Type:	ABS, AIR, DISK
Engine Brake:	CUMMINS C BRAKE
Dual Bunks:	2
Steer Axle Brakes:	6060% 60%
Drive Axle Brakes:	70% 70% (1)
	70% 70% (2)
	(3)
	(4)
	(5)
Backing Plates:	FRONT N / REAR N
Engine Serial:	75103446
Engine CPL (Hours):	NA (180)
Engine Family:	NCEXH0729XDA
APU | Condition (Make/Model):	N/A / NA (NA/NA)
Miscellaneous:	De-Ident.: No |Snap Test: Yes \ Pass |Figure 8 Test: N/A
CARB Equipment / Condition:	DEF / N/A

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		/ 32nd LUG /	/ 32nd LUG /
RIGHT	14 / 32nd HIGHWAY / V		
		/ 32nd LUG /	/ 32nd LUG /
FRONT			
		/ 32nd LUG /	/ 32nd LUG /
LEFT	13 / 32nd HIGHWAY / V		
		/ 32nd LUG /	/ 32nd LUG /

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs. REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

CONDITION REPORT

	ENGINE COMPARTMENT	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Engine oil - Condition & Level			
OK	Coolant - Level & Condition			
OK	Record coolant protection level			-32
OK	Radiator, reservoir, hoses			
OK	Fan hub / clutch, blade, shroud			
OK	Air intake - manifold, air-to-air & piping			
OK	Belt alignment, condition & adjustment			
OK	A/C compressor, clutch & brackets			
OK	Engine oil & fuel leaks			
OK	Steering gear, draglink, pump & hoses			
OK	Air compressor, governor & hoses			
OK	Exhaust system - manifold, turbo & piping			
OK	Starter & solenoid			
OK	Charging system - Record voltage			14.3

	INSIDE CAB AND SLEEPER	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Start engine - Listen for unusual noises			
OK	Clutch & clutch brake adjustment			
OK	Steering wheel, tilt column, shafts & u-joints			
OK	Glass - windshields, doors & mirrors			
OK	Windshield wipers & washers			
X	Mirrors - heat & power operation & condition			RIGHT MIRROR COVER DAMAGED
OK	Door hinges, latches, regulators & knobs			
OK	Seats - air operation & condition			
OK	Seat belts & bunk restraints			
OK	Upholstery, carpet, mats, etc....			
OK	Sleeper / cab privacy curtains & tracks			
OK	Cabinets, doors & hinges			
OK	Dash, gauges, switches & interior lights			
OK	Engine monitor display & LCD readout			
OK	Engine brake			
OK	Radio & speakers			
OK	Horns - city & air			
OK	Parking brake			
OK	Air pressure build up - Governed psi			
OK	Air leaks - dash, foot valve, shift knob, etc...			
OK	HVAC system, fans, control panels & vents			

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

CONDITION REPORT

	UNDER VEHICLE	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Front axle, king pins, tie rod & ends			
OK	Engine & transmission mounts			
OK	Frame & crossmembers			
OK	Air leaks on outside of truck			
OK	Drain wet tank - oil in air system?			
OK	Air dryer			
OK	Hydraulic brake lines & components			
OK	Brake hoses - cracking & chafing			
OK	Brake drums & linings			
OK	Wheel seals - leaks, etc...			
OK	Driveshafts, u-joints, yokes, carrier bearing			
OK	Transmission & rear axle - condition & leaks			
OK	Rear axle & suspension alignment			
OK	Suspension - springs, pins, hangers, etc...			
OK	Shocks, bushings & mount brackets			

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

CONDITION REPORT

	OUTSIDE OF TRUCK	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Mufflers, stanchion mounts, guards			
OK	Cab / sleeper air ride & mounting			
OK	Mirrors & mounting brackets			
OK	Lights & reflectors			
OK	Trailer cord, air lines, glad-hands, hangers			
X	Tires & wheels			8 MISSING TIRES
OK	Fuel tanks & mounting			
OK	Batteries, cables & terminals			
OK	5th wheel - plate, bushings, cylinder, etc...			
OK	Mud flaps, 1/4 fenders, brackets			

Additional Services	Requested	Status	Comments

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
Mirrors - heat & power operation & condition	RIGHT MIRROR COVER DAMAGED
Tires & wheels	8 MISSING TIRES
RIGHT FENDER	REPAIR & REFINISH
RIGHT DOOR LOCK	MISSING
RIGHT DOOR GLASS	DAMAGED
CAB BACK PANEL	REPAIR & REFINISH
8 ALUM WHEELS	MISSINGS
CAB SIDE PANEL DAMAGED	

COMMENTS:

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

1



2

3

4


5

6

7

8

9

10

11

12

13

14

15

16

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

17

18


19

20

21

22


23


24

25

26


27

28

29

30

31

32

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010


33

34

35

36

37

38

39

40


41

42

43

44

45

46

47

48

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
05/05/2023		0	PJ248237	

INSPECTOR: 6046
INSPECTION ID
157010

49	50	 51	 52
53	 54	 55	