DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

Year, Make:	2023 KENWORTH
Model:	T680
Full VIN:	1XKYD49X6PJ263844
Engine:	CUMMINS X15
HP:	500 (RATED) NA (ECU HP)
Clean air idle:	Yes
Sleeper (Size in):	INTEGRAL RAISED (76")
Wheelbase:	230"
Mileage:	2820 (ODOM) NA (ECU MILES) NA (HUB ODOM)
Trans Make | Model:	EATON/FULLER | ENDURANT
Trans Type:	AUTOSHIFT 12 SPD.
Suspension:	AIR RIDE
Front Axle:	MERITOR @ 13,200
Front Axle Pos:	SET BACK
Rear Axle:	MERITOR @ 40,000
Axle Type / Ratio:	TANDEM AXLE / 2.79 (RATIO)
3rd Axle:	NONE
GVW:	53,200
Power Steering:	Yes
Power Windows:	Dual
Air Cond:	Yes
Cruise Control:	Yes
Fuel Type:	DIESEL
Fuel Tanks / Material / Capacity:	2 / ALUMINUM / 135 (1) 135 (2) (3) (4)
Chassis Fairings:	FULL
Roof Fairings:	Yes Visor: NONE
Side Extenders:	Yes
Body Type | Cab Type:	Truck | CONVENTIONAL
Fifth Wheel:	AIR SLIDE
Tire Size (F) | Tire Size (R):	275/80 R22.5 | 275/80 R22.5
Steer Tire | Drive Tire Detail:	|
Cluster Test:	Yes \ Pass

Frame:	STEEL
Interior Type / Level:	PREMIUM / HIGH
Upholstery:	CLOTH & VINYL
Refrigerator:	No
Seat Suspension (High Back):	DUAL AIR (DUAL)
Bumper:	AERO
Air Horns:	SINGLE
New Paint |Interior Color |Paint Color:	No | GREY | WHITE
Identification:	NONE
Exhaust (Finish):	SINGLE HORIZONTAL (STAINLESS)
Air Cleaners	INTERNAL
Front Wheels | Rear Wheels:	ALUMINUM | ALUMINUM
Radio:	AM/FM CD
PTO:	No
Mirrors:	DUAL POWER
Wet Line Kit:	No
Brake Type:	ABS, AIR, DISK
Engine Brake:	CUMMINS C BRAKE
Dual Bunks:	2

Steer Axle Brakes:	80%	80%	
Drive Axle Brakes:	90%	90%	(1)
	90%	90%	(2)
			(3)
			(4)
			(5)

Backing Plates:	FRONT N / REAR N
Engine Serial:	80457091
Engine CPL (Hours):	NA (28)
Engine Family:	NCEXH0912XCA
APU | Condition (Make/Model):	No / (NA/NA)
Miscellaneous:	De-Ident.: No |Snap Test: Yes \ Pass |Figure 8 Test: No
CARB Equipment / Condition:	DEF / Passed Snap Test

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
		16 / 32nd LUG / V	16 / 32nd LUG / V
RIGHT	14 / 32nd HIGHWAY / V		
		16 / 32nd LUG / V	16 / 32nd LUG / V
FRONT			
		16 / 32nd LUG / V	16 / 32nd LUG / V
LEFT	14 / 32nd HIGHWAY / V		
		16 / 32nd LUG / V	16 / 32nd LUG / V

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs. REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

CONDITION REPORT

	ENGINE COMPARTMENT	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Engine oil - Condition & Level			
OK	Coolant - Level & Condition			
OK	Record coolant protection level			-34
OK	Radiator, reservoir, hoses			
OK	Fan hub / clutch, blade, shroud			
OK	Air intake - manifold, air-to-air & piping			
OK	Belt alignment, condition & adjustment			
OK	A/C compressor, clutch & brackets			
OK	Engine oil & fuel leaks			
OK	Steering gear, draglink, pump & hoses			
OK	Air compressor, governor & hoses			
OK	Exhaust system - manifold, turbo & piping			
OK	Starter & solenoid			
OK	Charging system - Record voltage			14.3

	INSIDE CAB AND SLEEPER	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Start engine - Listen for unusual noises			
OK	Clutch & clutch brake adjustment			
OK	Steering wheel, tilt column, shafts & u-joints			
OK	Glass - windshields, doors & mirrors			
OK	Windshield wipers & washers			
OK	Mirrors - heat & power operation & condition			
OK	Door hinges, latches, regulators & knobs			
OK	Seats - air operation & condition			
OK	Seat belts & bunk restraints			
OK	Upholstery, carpet, mats, etc....			
OK	Sleeper / cab privacy curtains & tracks			
OK	Cabinets, doors & hinges			
OK	Dash, gauges, switches & interior lights			
OK	Engine monitor display & LCD readout			
OK	Engine brake			
OK	Radio & speakers			
OK	Horns - city & air			
OK	Parking brake			
OK	Air pressure build up - Governed psi			
OK	Air leaks - dash, foot valve, shift knob, etc...			
OK	HVAC system, fans, control panels & vents			

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

CONDITION REPORT

	UNDER VEHICLE	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Front axle, king pins, tie rod & ends			
OK	Engine & transmission mounts			
OK	Frame & crossmembers			
OK	Air leaks on outside of truck			
OK	Drain wet tank - oil in air system?			
OK	Air dryer			
OK	Hydraulic brake lines & components			
OK	Brake hoses - cracking & chafing			
OK	Brake drums & linings			
OK	Wheel seals - leaks, etc...			
OK	Driveshafts, u-joints, yokes, carrier bearing			
OK	Transmission & rear axle - condition & leaks			
OK	Rear axle & suspension alignment			
OK	Suspension - springs, pins, hangers, etc...			
OK	Shocks, bushings & mount brackets			

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

CONDITION REPORT

	OUTSIDE OF TRUCK	OPTIONS 1	OPTIONS 2	COMMENTS
OK	Mufflers, stanchion mounts, guards			
OK	Cab / sleeper air ride & mounting			
OK	Mirrors & mounting brackets			
OK	Lights & reflectors			
OK	Trailer cord, air lines, glad-hands, hangers			
OK	Tires & wheels			
OK	Fuel tanks & mounting			
OK	Batteries, cables & terminals			
OK	5th wheel - plate, bushings, cylinder, etc...			
OK	Mud flaps, 1/4 fenders, brackets			

Additional Services	Requested	Status	Comments

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM	DESCRIPTION / COMMENTS
FRONT BUMPER LEFT SIDE VALANCE	DAMAGED
RIGHT SIDE REAR CHASSIS LOWER SKIRT	DAMAGED

COMMENTS:

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

1

2

3



4

5

6

7

8


9

10

11

12

13

14

15

16

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32

DEKRA

DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR INSPECTION

CLIENT
362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
04/06/2023		1017	PJ263844	

INSPECTOR: 6046
INSPECTION ID
156993

33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48