



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

09/08/2020

FLEET NAME

VIN (LAST 8)

FT095212

PO NUMBER

INSPECTOR: 5750

INSPECTION ID

125075

| | | | |
|--|------------------|------------------------|-------------------|
| Year, Make: | 2015, JOHN DEERE | Full VIN: | 1TC250BGAFT095212 |
| Model: | 2500B | Engine Make: | JOHN DEERE |
| Engine Model: | | Clean air idle: | |
| Classification: | | | |
| Note and photograph any body damage including scrapes, dents and glass: | | | |
| NONE | | | |
| Note and photograph any major oil or fluid leaks: | | | |
| NONE | | | |
| Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls. | | | |
| NONE | | | |
| Note any unusual engine noises or knocks: | | | |
| GOOD | | | |
| List and photograph any tires with uneven wear: | | | |
| GOOD | | | |
| Additional Comments: | | | |
| ENGINE HOURS 2054 | | | |

| Additional Services | Requested | Status | Comments |
|---------------------|-----------|--------|----------|
|---------------------|-----------|--------|----------|



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
504 - Wells Fargo MSG
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/08/2020 | | FT095212 |

INSPECTOR: 5750
INSPECTION ID
125075



VIN



4



45 DEGREE BEAUTY SHOT



1



ADDITIONAL 2



ADDITIONAL 6



SEAT



HOURS



2



3



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5



ADDITIONAL 7



ADDITIONAL 8