









FOR PASSENGER
FEDERAL LAW PROHIBITS
OPERATION OF THIS
VEHICLE WHILE ANY
PERSON IS STANDING
FORWARD OF THIS WHITE LINE







PREVOST

X3

WARNING
WHEN OPENING DOOR
KEEP CLEAR OF ITS
MOVING PARTS



DO NOT PARK WITHIN 3 METERS

OPTIMA
Coach Tours and Charter











PREVOST

X3
45

OST



PI

Print Date: September 23, 2020 2:21 PM

VIN	
Vehicle Make	
Model	
Model Year	

Vehicle Components

Component	Description	Serial Number	Software Version	Notes
Transmission	Allison 3000 (900L 5R) Gen	B43B60A2527900105	N/A	u1000 (44pin/15705 (CAN))

Vehicle Key Data Points

Parameter Description	Value	Parameter Description	Value
Idle Fuel Used	Not Available	DPF Soot Level	Not Available
Total Idle Hrs	Not Available	DPF Delete	Not Available
Total Engine Hrs	Not Available	Battery Potential	Not Available
Cruise Set Limit	Not Available	Hours Speed Limit	Not Available
Total Avg Fuel Econ	Not Available	Malfunction Indicator Lamp	Off
Red Stop Lamp	Off	Amber Warning Lamp	Off
Protect Lamp	Off	Parking Brake Switch	Not Available
DPF Lamps Command	Not Available	Exhaust System High Temporal	Not Available
ABS Control Status	Not Available	ABS Control Status, Trailer	Not Available
Engine Speed	601 rpm	Odometer	230,156.63 mi
Engine Odometer	230,156.63 mi	Instrument Cluster Odometer	Not Available

Vehicle Issues



No Active Issues Found

Faults

Status	Component	Description	Lookup Code	PM	Count
Resolved	Exhaustman 1	TCM Reset from Fault Log	#100	01	100



PREVOST®

MANUFACTURED BY: PREVOST
FABRIQUE PAR : STE - CLAIRE, QUE.

DATE OF MFG.
DATE DE FAB.

12/15

EC

G. V. W. R. :

P. N. B. V. : 24040 KG. (53000 LBS).

AXLES/
ESSIEUX

G. A. W. R. /
P. N. B. E.

TIRES/
PNEUS

RIMS/
JANTES

COLD
INFLATION
PRESS. /
PRESS. A
FROID
KPA (PSI)

SINGLE
OR DUAL
SIMPLE
OU
DOUBLE

	KG	(LBS)				
FRONT : AVANT :	7484	(16500)	315/80R22.5 (L)	22.5X9	827 (120)	S
INT : DIFF. :	10206	(22500)	315/80R22.5 (L)	22.5X9	586 (85)	D
REAR : TANDEM :	6350	(14000)	315/80R22.5 (L)	22.5X9	689 (100)	S

THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE
SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VEHICLE IDENTIFICATION NO.
NO. IDENTIFICATION VEHICULE

2PG6334387

#408301

TYPE : BUS B/A







PREVOST

X3



NO STANDEES

X3
45



BAILO TOU STEP

90-6561
90-6561
90-6561





(P)

r/min x 100

PREVOST



86 °F



→ Empty

403 mi

75 g



1

2

mi

5456.9


5456.5

13:41



230147.9mi

ULTRA LOW SULFUR DIESEL FUEL ONLY



Acquiring vehicle information...

Vehicle

Engine

Allison 3000M4000 5th Gen

Vehicle Information:

VIN: Not Available
 Manufacturer: Not Available
 Model Year: Not Available

Status	Component	Description	Lookup Code	FME	Count
Interact	Transmission	TDM Power Input Signal Low	P0862	ISB	N/A



Clear Faults















No Active Issues Found

Repair Mentor

Vehicle

Engine

Allison 3000/4000 5th Gen

Vehicle Information

VIN: Not Available

Manufacturer: Not Available

Model Year: Not Available

Repair Mentor

JPRO® Repair Mentor

Let us help guide your repair decisions

Any discovered issues affecting vehicle health are listed below in preferred diagnostic order.

Click an issue to see more information.

To re-open this form, click the vehicle health button in Vehicle Readiness.

Current Vehicle Issues



No Active Issues Found

☐ Do Not Use Repair Mentor For This Connection

Repair Mentor may be completely disabled in Preferences.

No Active Issues Found

There does not appear to be any critical vehicle issues active on the vehicle. Non-critical issues that affect overall vehicle health may still exist.

Click 'Close' to continue with this diagnostic session.

Begin Diagnostic

Close

Lookup Code / EPI / Count

P0B02 / N/A / N/A

Total Life Hrs

00 hrs

Idle Fuel Stand

00 gal



Type here to search




2:41 PM 9/23/2020











HOT
COLD

VOLVO PENTA

B-134a

CAUTION



