2018 VOGEL SUPER 2000-3I

UNIT: 1174.0209

Download Reconditioning Printout






























































































































UNIT SPECS

Customer

Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)
Please call Pickup Support for location information
Lakeville, MN 55044

CHASSIS

Screed Tow Arms Rating:

Good

Screed Bottom Plate

Rating: Good

Hopper Wings

Rating:

Good

Metering Gates

Powered

Rating:

Good

Auger/ Screw Condition

Rating:

Good

Feed Conveyors Rating: Good

Push Rollers Rating: Good

Screed Heaters Not operationally checked

Screed Slope Adjustment Not operationally checked

Screed Crown Adjustment Not operationally checked

Extension Tubes Rating: Good

End Gates Rating: Good

Limited Function Check (Chassis)

The main components were operational in a limited check.

Screed

Vogele Minimum Paving Width: 10 ft - Maximum Paving Width: 20 ft Screed

CONTROL STATION

Hydraulic Controls Rating: Good

Steering Control Rating: Good

Drivetrain Controls Rating:

Good

Oil Pressure

No oil pressure indicator

Warning Lights Inoperable

Screed Control Switches

Rating: Good

Gauges Operational

Hour Meter (Pre-inspection) 2909 hrs

Hour Meter 2909 hrs, Did not change during the inspection

Limited Function Check (Control Station)
The main components are in place and operational as noted.



DRIVETRAIN

Transmission Type Hydrostatic Drive

Transmission Rating: Good

Left Drive Motor Rating: Good

Right Drive Motor Rating: Good

Left Final Drive Rating: Good

Right Final Drive Rating: Good

Limited Function Check (Drivetrain) The drivetrain was operational.

ENGINE

Blow-by (Subjective Visual Observation) No noticeable vapor or pressure



Starter Operational

Radiator Rating:

Good

Oil Leaks No dripping leaks

Limited Function Check (Engine) The engine started and ran.



GENERAL APPEARANCE

Year 2018 Make Vogel

Model

Super 2000-3i

Serial Number / VIN 1174.0209

Hour Meter /Odometer Usage Reading (Start) 2909 mi

Hour Meter / Odometer 2909 hrs

Condition

Overall Condition for Age:, Good

Exterior Lights Operational

Serial 1174.0209

Seller Reference Number Seller Reference or Fleet Number:, 86E4CF09

HYDRAULICS

Pumps (Hydraulics)

Rating: Good

Valves

Rating:

Good

Hydraulic Tank

Rating:

Good

Hydraulic Motors

Rating: Good

Hoses (Hydraulics)

Rating: Good

Hopper Wing Cylinders

Rating: Good

Screed Tow Point Cylinders

Rating: Good

Screed Lift Cylinders

Rating:

Good

Screed Extension Cylinders Rating: Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

LOGISTICS INFORMATION

Shipping Dimensions See manufacturers specs

General Shipping Information

Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? Yes: Is the unit wider than 8'6"? No: Is the unit taller than 12'? No: Inflated Tires - item can roll? No: Noticeable fluid leaks?

Road Related Shipping Info

Yes: Lights Operate? Yes: Brakes Operate? Yes: Tires OK?

SAFETY

Travel Alarm Operational

Horn Operational

Seat Belts Not equipped

Safety Lock Out/Stop Operational

Current Safety Manual

Current Operator/Maintenance Manual

UNDERCARRIAGE

Undercarriage

Rubber Track Undercarriage: 18 in Rubber Tracks

RUBBER TRACK UNDERCARRIAGE

Left Track Belt Condition Minor cuts

Left Rubber Belt Drive Lugs No visible damage

Left Grouser Height

Right Track Belt Condition
Minor cuts

Right Rubber Belt Drive Lugs
No visible damage

Right Grouser Height
18 mm

MODEL DESCRIPTION

Model Description
Track

RECONDITIONING	
Warning Lights - Inoperable	\$500
Track Belt Condition - Minor cuts	\$6,500
Total	\$7,000