

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvig.com

Make:	Bobcat	Type:	Compact Track Loader	Inspector:	CM
Model:	T450	Hours:	2895	Inspection Date:	1/13/2025
SN:	B4RG11163	Year:	2021		

## SPECIFICATIONS

ROPS:	<b>Yes</b>	Hours:	<b>2895</b>			
Enclosed Cab:	<b>Yes</b>	Cab Heat:	<b>Yes</b>	Cab A/C:	<b>Yes</b>	Controls: <b>Selectable Joystick Controls</b>
Attachment on Machine:	56" Bucket					
Additional Attachments:	N/A					
2-Speed:	<b>No</b>	Engine MFR:	<b>BOBCAT</b>	<b>Tracks</b>		
High Flow Hydraulics - Sticker:	<b>No</b>	Power Bob-Tach:	<b>Yes</b>	Keyless Start:	<b>Yes</b>	
Backup Camera:	<b>No</b>	Ride Control:	<b>No</b>	Deluxe Instrumentation:	<b>Yes</b>	
Hydraulic X-Change:	<b>No</b>					
Comments and Defects:	<b>HAS RADIO,</b>					

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

TRACKS	
Make: BOBCAT Part #: 6682177 Measure: 32 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:	Make: BOBCAT Part #: 6682177 Measure: 32 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

## CONDITION REPORT

	Check	Comments / Deficiencies
X	Visual Inspection	MUD,
X	Operational Test	BATTERY DEAD / HAD TO JUMP START AND PRIME FUEL SYS SEVERAL TIMES/ NEEDS DIAGNOSED POSSIBLE FUEL SYSTEM ISSUE
✓	Lift Cylinders	NO LEAKS
✓	Tilt Cylinders	NO LEAKS
N/A	Boom Arms Operations	
✓	Seat	GOOD CONDITION
X	Tailgate Lights	BROKEN LEFT TAIL
✓	Working Lights	GOOD CONDITION
✓	Front Door	NO DAMAGES
✓	Rear and Top Window	NO DAMAGES
✓	Side Glass Complete	NO DAMAGES
N/A	Boom Arms Damages	
✓	Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓	Mufflers	GOOD CONDITION
✓	ROPS Condition	GOOD CONDITION
✓	Power Bob-Tach Condition	
✓	Cab A-C Condition	WORKING
✓	Cab Heat Condition	WORKING
X	Intake Screen	RUST DAMAGED BENT
✓	Eng. Compartment	
N/A	Hydraulic X-Change Condition	
X	Customer Decals Visible on Unit	YES
✓	Error Codes	

PHOTOS



Front Left



Front Right





PHOTOS



Rear



Seating / Interior





PHOTOS





PHOTOS



PHOTOS





PHOTOS



PHOTOS





PHOTOS



PHOTOS





PHOTOS

