



Aspen Field Services

Job #: 28127 /

Serial #: 1FDFE4FS5HDC67310

2018 FORD CHAMPION

For more information, visit:

wellsfargo.com/equimentseller



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/Am6EzE76MGMNMvp4j/full_report_0028127_Am6EzE76MGMNMvp4j.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details

Year	2018
Make	Ford
Model	Champion
VIN	1FDFE4FS5HDC67310
Type	Bus
Date Of Inspection	2/25/2021
Location of Inspection	Polynesian Adventure Tours - 4031 Halau St Bay #4, Lihue, HI, 96766
Odometer	137752
GVWR	14,500
Engine. Make	Ford
Active Warnings	Check Engine Light
Drivers Seat	Good Condition
Passenger Seat	Good Condition
Transmission	Automatic
Fuel Type	Gasoline



Aspen Field Services

Job #: 28127 /

Serial #: 1FD FE4FS5HDC67310

For more information, visit:

wellsfargo.com/equipmentseller

2018 FORD CHAMPION

Inspection Details Cont'd	
Cab Glass	Good Condition
Cab Steps	Good Condition
Operational Test	Operational
Front Left Tire Condition	Good Condition
Front Left Tire Brand	Hankook
Front Left Tire Size	LT225/75R16
Front Left Tire Tread Depth Measurement	6/32"
Front Right Tire Brand	Hankook
Front Right Tire Size	LT225/75R16
Front Right Tire Tread Depth Measurement	7/32"
Front Right Tire Condition	Good Condition
Back Left Tire Brand	Hankook
Back Left Tire Size	LT225/75R16
Back Left Tire Tread Depth Measurement	8/32"
Back Left Tire Condition	Good Condition
Inner Back Left Tire Tread Depth Measurement	8/32"
Inner Back Left Tire Condition	Good Condition
Back Right Tire Brand	Hankook
Back Right Tire Size	LT225/75R16
Back Right Tire Tread Depth Measurement	8/32"
Back Right Tire Condition	Good Condition
Inner Back Right Tire Tread Depth Measurement	7/32"
Inner Back Right Tire Condition	Good Condition
Mismatched Tires	No
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition
Radio	Yes
Engine Hood	Good Condition
Storage Door	Opens and Closes
Engine Compartment	Clean
Coolant	Above 50%
Head Lights	Good Condition
Tailgate Lights	Good Condition
Backup Alarm	Operational
Customer Decals Visible On Unit	Yes
Comments	The check engine light is currently on display.

Inspection Details Cont'd