



Aspen Field Services

Job #: 25599 /

Serial #: 86599

For more information, visit:

wellsfargo.com/equipmentseller

2017 MCCLOSKEY R230 HIGH ENERGY
SCREENER



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/su9BcGAdEma7BRueu/full_report_0025599_su9BcGAdEma7BRueu.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	McCloskey
Model	R230
Serial Number	86599
Type	High Energy Screener
Inspection Date	12/3/2020
Location of Business	JJ Kane Auctioneers - Rome; 5835 Success Dr, Rome, NY 13440
Engine Compartment	Dirty
Engine MFR	Caterpillar
Hours	4521
Hydraulic Lines	No Leaks
Hydraulic Cylinders	No Leaks
Left Track Condition	Fair Condition - Tension Adjustment Needed
Left Track Depth Percentage	NA Metal Tracks
Left Track Idler	Good Condition



Aspen Field Services

Job #: 25599 /

Serial #: 86599

For more information, visit:

wellsfargo.com/equipmentseller

2017 MCCLOSKEY R230 HIGH ENERGY
SCREENER

Inspection Details Cont'd	
Left Track Sprocket	Good Condition
Left Track Rollers	Good Condition
Right Track Condition	Fair Condition - Tension Adjustment Needed
Right Track Depth Percentage	NA Metal Tracks
Right Track Idler	Good Condition
Right Track Sprocket	Good Condition
Right Track Rollers	Good Condition
Conveyor Belt Condition	Good Condition
Conveyor Belt Rollers	Good Condition
Grab Irons	Good Condition
Steps / Ladders	Damaged - Unable to Unlatch
Platform	Good Condition
Body Panels	Good Condition
Emergency Stop	Yes
Controls	Standard
Side Conveyor Belts	4
Landing Gear	Good Condition
Fuel Type	Diesel
Horse Power	225 hp
Transport Height	11' 5.8"
Transport Length	55' 8"
Transport Width	9' 10"
Weight	82,000 lbs
Screenbox Dimensions	6' x 20'
Screen Box	Fair Condition
Hopper	Good Condition
Operational	Yes
Comments	The tracks on the unit are sagging and the tension needs to be adjusted. The sprockets, idlers, and rollers all appear to be in good shape. The engine starts and runs smoothly with no indication of any problems. There are also no signs of leaks in the engine or among the hydraulic lines and cylinders. The belts and rollers all appear to be in good condition. The screen box is in fair condition showing wear and tear among the cutting edges. The step ladder pins are

Inspection Details Cont'd



Aspen Field Services

Job #: 25599 /

Serial #: 86599

For more information, visit:

wellsfargo.com/equipmentseller

2017 MCCLOSKEY R230 HIGH ENERGY
SCREENER

bent preventing them from folding down.
