



Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

Report # 30411

August 17, 2026

Phoenix, AZ

UNIT	3
VIN	1NKZDB0X1TJ185676
YEAR	2026
MAKE	KENWORTH CNG
MODEL	T880
CAB/SLEEPER TYPE OPTIONS	Day Cab
FUEL	Natural Gas / 2
FRAME TYPE	Steel / Air Slide Fifth Wheel
ENGINE	Cummins / X-15 / 500HP
TRANSMISSION	Automatic / ALLISON / 4500 RDS / 6sp
OPTIONS	AC, Heat, Cruise Control / Power Mirrors / Power Windows / AM, FM / Single Air, Driver High Back
COLOR	BLACK/SILVER Exterior / GRAY Interior
COLLISION DETECTION	Yes / Front
WHEEL TYPE	F: Aluminum / R: Aluminum / 295/75R/22.5
MILEAGE/HOURS	74433 / 3101
EXHAUST	Single / Vertical / Chrome / SCR
AXLE	F 14320 / 46,000R Drive / 60320 LBS Total
CHASSIS	238WB / Air / 6x4



BRAKES

Disk 70%	Disk 70%
Disk 60%	Disk 60%
Disk 50%	Disk 50%

TIRES

12/32 V		14/32 V	
18/32 R1	18/32 R1	18/32 R1	18/32 R1
18/32 R1	18/32 R1	10/32 R1	10/32 R1



Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

Report # 30411

August 17, 2026

Phoenix, AZ

CONDITION OVERVIEW

STARTS: Yes	DRIVES: Yes	FLUIDS : Good	BODY DAMAGE: Yes	LIGHTS: Good
HORN: Good	WARNING LIGHTS ON: No			

RECOMMENDED REPAIRS AND ESTIMATE

DESCRIPTION	CONDITION	PARTS	LABOR
FRONT BUMPER	CRACKED LEFT SIDE	\$1,200.00	\$250.00
WINDSHIELD	2 ROCK CHIPS	\$600.00	\$250.00
left lite damage, minor paint damage		\$250.00	\$400.00
		TOTAL:	\$2,950.00



Custom Inspection Solutions


(678) 956-4485

<mailto:info@custom-inspection-solutions.com>


Report # 30411

August 17, 2026

Phoenix, AZ




Picture Taken: Aug 14, 2026 1:42 PM



Picture Taken: Aug 14, 2026 1:42 PM



Picture Taken: Aug 14, 2026 1:42 PM



Picture Taken: Aug 14, 2026 1:42 PM




Picture Taken: Aug 14, 2026 1:43 PM



Picture Taken: Aug 14, 2026 1:43 PM



Picture Taken: Aug 14, 2026 1:43 PM



Picture Taken: Aug 14, 2026 1:44 PM



Picture Taken: Aug 14, 2026 1:45 PM



Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

Report # 30411

August 17, 2026

Phoenix, AZ



Picture Taken: Aug 14, 2026 1:45 PM



Picture Taken: Aug 14, 2026 1:45 PM



Picture Taken: Aug 14, 2026 1:45 PM



Picture Taken: Aug 14, 2026 1:45 PM




Picture Taken: Aug 14, 2026 1:45 PM



Picture Taken: Aug 14, 2026 1:45 PM



Picture Taken: Aug 14, 2026 1:46 PM



Picture Taken: Aug 14, 2026 1:46 PM



Picture Taken: Aug 14, 2026 1:46 PM



Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

Report # 30411

August 17, 2026


Phoenix, AZ




Picture Taken: Aug 14, 2026 1:47 PM



Picture Taken: Aug 14, 2026 1:49 PM



Picture Taken: Aug 14, 2026 1:49 PM




Picture Taken: Aug 14, 2026 1:49 PM



Picture Taken: Aug 14, 2026 1:49 PM



Picture Taken: Aug 14, 2026 1:50 PM



Picture Taken: Aug 14, 2026 1:50 PM



Picture Taken: Aug 14, 2026 1:50 PM



Picture Taken: Aug 14, 2026 1:51 PM



Custom Inspection Solutions

(678) 956-4485

<mailto:info@custom-inspection-solutions.com>

Report # 30411

August 17, 2026

Phoenix, AZ



Picture Taken: Aug 14, 2026 1:51
PM



Picture Taken: Aug 14, 2026 1:51
PM