


2019 RUTHMANN REACHMASTER FALCON FS 95

UNIT: 18041

[Download Reconditioning Printout](#)



UNIT SPECS

Customer

Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)

Please call Pickup Support for location information

Humble, TX 77396

GENERAL APPEARANCE

UID

18041



Pre-Operational Checks

Confirm Fluids Checked: Hydraulic Fluid. N/A: Engine Coolant. N/A: Engine(s) Oil. N/A: Transmission Fluid. N/A: Fuel Level



Paint

No visible damage



Sheet Metal (Fiberglass) Condition

No visible damage or missing components



FEATURES

Power Source

Electric



Max Lift Height

95 ft Max Lift Height, 440 lb Max Weight Capacity, Platform Extension, Power to Platform, Onboard Generator, Stabilizers, Upper Control Box



SAFETY

Travel Alarm

Operational



Horn

Operational



Current Safety Manual

No



Current Operator/Maintenance Manual

No



CONTROL STATION

Hour Meter/Odometer (Start)

216.8 hrs



Hour Meter/Odometer

216 hrs, Operational hour meter



Gauges

Operational



Function Controls

Rating:

Good



Warning Lights

Operational



Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Console

No visible damage or missing components



Emergency Shut Off Switch

Operational



Safety Control Foot Switch

Operational

Rating:

Good



Upper Function Controls

Rating:

Good



Limited Function Check (Control Station - Upper)

The main components are in place and operational as noted.



ELECTRIC OPERATING SYSTEM

Operating Voltage

24 Volts



Battery

Functioned during the inspection



Cables and Connections Condition

No visible damage or missing components



Battery Charger

Included 24 Volt, Single Phase



DRIVETRAIN

Drive Motors

Rating:

Good



Limited Function Check (Drivetrain - Boom Lift)

The drivetrain was operational.



HYDRAULICS

Pumps (Hydraulics)

Rating:

Good



Valves

Rating:

Good



Hydraulic Tank

Rating:

Good



Lift Cylinders

Rating:

Good



Steering Cylinders

Rating:

Good



Outrigger Cylinders

Rating:

Good



Limited Function Check (Hydraulics)

The hydraulic system was operational.



CHASSIS

Brake System

The brake system functioned, stopping and holding the machine.

Rating:

Good



Steering Linkage

Rating:

Good



Frame Condition

Rating:

Good



Platform Condition

No visible damage or missing components



Platform Condition Rating

Rating:

Good



Platform Extension

Rating:

Good



Left Front Tire

No visible defects



Left Rear Tire

No visible defects



Right Rear Tire

No visible defects



Right Front Tire
No visible defects



Wheel Condition
No visible damage or missing components



Wheel Studs, Nuts, Lugs
Rating:
Good



Outriggers/Stabilizers
Rating:
Good



Limited Function Check (Scissor Lift)
The main components appear to be in place and operational.



RECONDITIONING