

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
**203-628-4325** [info@cvigna.com](mailto:info@cvigna.com)

Make:	Bobcat	Type:	Mini Excavator	Inspector:	DAV
Model:	E35 R2	Hours:	821		
SN:	B4P313605	Year:	2023	Inspection Date:	3/20/2025

## SPECIFICATIONS

ROPS:	<b>Yes</b>	Hours:	<b>821</b>		
Enclosed Cab:	<b>No</b>	Cab Heat:	<b>No</b>	Cab A/C:	<b>No</b>
Attachment on Machine:	24" Bucket				
Additional Attachments:	N/A				
2-Speed:	<b>Yes</b>	Engine MFR:	<b>BOBCAT</b>	<b>Tracks</b>	
High Flow Hydraulics - Sticker:	<b>No</b>	Power Bob-Tach:	<b>No</b>	Keyless Start:	<b>Yes</b>
Backup Camera:	<b>No</b>	Ride Control:	<b>No</b>	Deluxe Instrumentation:	<b>No</b>
Hydraulic X-Change:	<b>No</b>				
Comments and Defects:	<b>THE UNIT WAS IN GOOD OPERATIONAL CONDITION. TRACK WERE WORN.,</b>				

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
[wellsfargo.com/equipseller](http://wellsfargo.com/equipseller)



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
**203-628-4325** [info@cvigna.com](mailto:info@cvigna.com)

## Tire Fault Legend

C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

## TRACKS

Make: BOBCAT  
Part #: NA  
Measure: 8 / 32  
Condition: POOR  
Tread Remaining: Under 50%  
Fault:

Make: BOBCAT  
Part #: NA  
Measure: 7 / 32  
Condition: POOR  
Tread Remaining: Under 50%  
Fault: C

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipmentseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
**203-628-4325** [info@cvigna.com](mailto:info@cvigna.com)

## CONDITION REPORT

	Check	Comments / Deficiencies
✓	Visual Inspection	CLEAN
✓	Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓	Lift Cylinders	NO LEAKS
✓	Tilt Cylinders	NO LEAKS
✓	Boom Arms Operations	WORKING
✓	Seat	GOOD CONDITION
✓	Tailgate Lights	GOOD CONDITION
✓	Working Lights	GOOD CONDITION
N/A	Front Door	
N/A	Rear and Top Window	
N/A	Side Glass Complete	
✓	Boom Arms Damages	NO DAMAGES
✓	Rear Door	OPENS AND CLOSSES AND STAYS CLOSED
✓	Mufflers	GOOD CONDITION
N/A	ROPS Condition	
✓	Power Bob-Tach Condition	OPERATIONAL
N/A	Cab A-C Condition	
N/A	Cab Heat Condition	
✓	Intake Screen	GOOD CONDITION
✓	Eng. Compartment	
✓	Hydraulic X-Change Condition	OPERATIONAL
N/A	Customer Decals Visible on Unit	
✓	Error Codes	
X	Right Track Depth Percentage	RIGHT TRACK UNDER 50%
X	Right Track Faults	TRACK IS CUT
X	Left Track Depth Percentage	LEFT TRACK UNDER 50%

PHOTOS



Front Left



Front Right



Rear



Seating / Interior



PHOTOS



## PHOTOS





PHOTOS





# PHOTOS





## PHOTOS





## PHOTOS





PHOTOS





PHOTOS





PHOTOS





PHOTOS





## PHOTOS



## PHOTOS

