



Video:



PHOTOS: Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/oy9hHxvBEdcnZejgg/full\\_report\\_0033827\\_oy9hHxvBEdcnZejgg.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/oy9hHxvBEdcnZejgg/full_report_0033827_oy9hHxvBEdcnZejgg.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	Not Available
Make	Dynapac
Model	CC4200 VI
PIN	10000385LJA022025
Type	Roller
Inspection Date	9/14/2021
Location of Inspection	JJ Kane Auctioneers - Chester; 13301 Great Coastal Dr, Chester VA, 23836
Attachment(s)/ Accessory(s)	NA
Attachment Serial Number	NA
Hours	NA - See Notes
Active Warnings	NA - See Notes
Enclosed Cab	No
Cab A-C	No
Cab A/C Condition	NA
Cab Heat	No



# Aspen Field Services

Job #: 33827 /

Serial #: 10000385LJA022025

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

DYNAPAC CC4200 VI

Inspection Details Cont'd	
Cab Heat Condition	NA
Seat	Good Condition
Backup Camera	No
Keyless Start	No
Interior	Fair Condition
Operational Test	NA - See Notes
Front Roller Condition	Fair Condition
Front Roller Width	66"
Front Roller Diameter	50.5"
Front Roller Thickness	5/8"
Back Roller Condiiton	Fair Condition
Back Roller Width	66"
Back Roller Diameter	50.5"
Back Roller Thickness	5/8"
Hydraulic Hoses / Lines	Good Condition
Articulation Cylinder	Good Condition
Engine Panel	Good Condition
Engine MFR	Not Available
Engine Compartment	Dirty
ROPS Condition	Good Condition
Side Glass Complete	NA
Cab Steps	Good Condition
Grab Irons	Good Condition
Working Lights	NA - See Notes
Tailgate Lights	NA - See Notes
Comments	The unit does not run, which prevented us from verifying the hours and the regular operations of the unit. The exterior and interior of the cab are in overall good condition with little wear and tear visible.

## Inspection Details Cont'd