



Aspen Field Services

Job #: 27785 /

Serial #: 998871015

For more information, visit:

wellsfargo.com/equipmentseller

TITAN RAINCAR



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/rXrCDJD37h2Eb7R7Y/full_report_0027785_rXrCDJD37h2Eb7R7Y.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	Not Available
Make	Trackmobile
Model	Titan
Serial Number	998871015
Type	Railcar
Inspection Date	2/5/2021
Location of Business	JJ Kane Auctioneers, 14354 Dearborn Ave, South Beloit, IL, 61080
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Driver Seat	Good Condition
Passenger Seat	Good Condition
Controls	Standard
Keyless Start	None
Foot Pedals	NA
Hours	17039



Aspen Field Services

Job #: 27785 /

Serial #: 998871015

For more information, visit:

wellsfargo.com/equipseller

TITAN RAINCAR

Inspection Details Cont'd	
Cab A-C	Yes
Cab Heat	Yes
Cab A/C Condition	Good Condition
Cab Heat Condition	Good Condition
Backup Camera	Yes
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Goodyear: Not Available
Front Right Tire Depth Percentage	Above 50%
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	21/32"
Front Left Tire Part Number	Goodyear: Not Available
Front Left Tire Depth Percentage	Above 50%
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	25/32"
Back Right Tire Part Number	Goodyear: Not Available
Back Right Tire Depth Percentage	Above 50%
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	20/32"
Back Left Tire Part Number	Goodyear: Not Available
Back Left Tire Depth Percentage	Above 50%
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	28/32"
Mismatched Tires	No
Front Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Back Left Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Right Side Wheel Cylinders	Good Condition
Left Side Wheel Cylinders	Good Condition
Tailgate Lights	Good Condition
Working Lights	Good Condition
Cab Door	Good Condition
Passenger Door	Good Condition
Side Glass Complete	Yes
Muffler	Good Condition
Intake Screen	Good Condition
Engine Door	Good Condition

Inspection Details Cont'd	
Engine Compartment	Dirty
Engine MFR	Cummins
Engine Serial Number	73881910
Customer Decals Visible on Unit	Yes
Railings	Good Condition
Steps	Good Condition
Comments	