



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
09/09/2020		1805	J3081105	

INSPECTOR: 5449

INSPECTION ID

125348

Year	2018	Make	VAN HOOL
Model	CX45	VIN	YE2XC81B7J3081105

SPECIFICATION WORKSHEET

Interior Options	
Interior Color:	GRAY

Steering Options	
Power Steering?:	Yes

Engine Options A	
Eng Make:	DETROIT
Eng Model:	DD13
Eng Serial:	47194150552918
Eng HP:	450
Cruise:	Yes
Clean air idle:	No

Overall Condition	
Overall Length:	45
Overall Height:	11'10"
Overall Width:	102

Engine Options B	
Odometer:	85133
Hub odometer:	N/A
ECU HP:	450.58
ECU Miles:	84153
Eng Hours:	3467

Miscellaneous	
Seating Capacity:	56
Electronic Engine Controls:	Yes
Full Gauge Package:	Yes
Wraparound Dash:	Yes
Power Mirrors:	Yes
Tilt / Telescopic Steering Wheel:	No
AirRide Driver's Seat:	Yes
Restroom:	Yes
PA System:	Yes
Audio - Video System:	Yes
Number of Video Monitors:	6
Multi-Disc CD Changer:	No
Individual multi-Channel Audio System:	Yes
Global Positioning System:	Yes
In Motion Satellite TV System:	Yes
Road Viewing Monitor System:	Yes
Wheelchair Lift:	No
Underfloor Storage with Lift:	No
Parcel Rack Storage with Lift:	No
Traction Control:	Yes
Power Windshield Sun Visors:	Yes
Tour Guide Seat:	No
Other:	
Was Unit driven In ?:	Yes
Did Unit need to be jump started ?:	No
Was Unit towed in ?:	No
Did Unit start and run ?:	Yes
Unit Condition:	VERY GOOD
If Unit is not driveable or will not start, Explain:	
Any extra options or features not listed on front page and any additional comments:	

Engine Options C	
Eng Brake:	DRIVELINE
Fuel:	DIESEL
FT1 Capac (Gal):	N/A

Exterior Options A	
Air Horns:	SINGLE
Mirrors:	HEATED DUAL POWER
Exterior Color:	WHITE

Axle / Susp Options	
WheelBase (In):	N/A
Rear Ratio:	N/A
F Axle (lbs):	17,640
R Axle (lbs):	27,575
GVWR (lbs):	54,000
Suspension:	AIR RIDE
Tag Axle Capacity:	17,640
Rear Axle Model:	N/A
Independent Front Suspension:	Yes
Full Coach Raise and Lowering Susp.:	Yes
Tag Axle Unloading System:	Yes
Front Susp. Kneeling System:	Yes

Transmission Options	
Trans Make:	ALLISON
Trans Model:	B 500
Trans Speed:	12



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT
 362 - Wells Fargo Equipment Management
 INSP DATE | FLEET NAME | UNIT NUMBER | VIN (LAST 8) | PO NUMBER
 09/09/2020 | | 1805 | J3081105 |










INSPECTOR: 5449
INSPECTION ID
 125348

Brakes Options	
ABS:	YES
HYD:	NO
AIR:	YES
DISK:	YES
DRUM:	NO
Brake Plates:	FRONT N / REAR N

Brakes	
Drive Axle Brakes:	(1)
	(2)
	(3)
	(4)
	(5)

Tires [Front]	
Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

Tires [Rear]	
Size:	315/80 R22.5
Wheels:	ALUMINUM
Detail:	

	STEER AXLE	DRIVE AXLE #1	DRIVE AXLE #2
RIGHT	9 / 32nd HIGHWAY / V 	18 / 32nd HIGHWAY / V 	15 / 32nd HIGHWAY / V 
		18 / 32nd HIGHWAY / V 	/ 32nd / 
FRONT		17 / 32nd HIGHWAY / V 	/ 32nd / 
	LEFT	7 / 32nd HIGHWAY / V 	5 / 32nd HIGHWAY / V 

Brake Legend

BD = DRUM HAS MORE THAN 1/16 INCH LIP
CL = CRACKED LINING
LS = LEAKING SEAL(S)

Tire Legend

C = CUT D = DRY ROT F = FLAT
M = MISMATCHED TIRES/CASING
MA = MISMATCHED AXLES (FRONT vs. REAR)
V = VIRGIN W = IRREGULAR WEAR
R = RECAP: 1 = ONCE, 2 = TWICE, 3 = 3 TIMES

Tread Legend

H = HIGHWAY L = LUG



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
09/09/2020		1805	J3081105	

INSPECTOR: 5449

INSPECTION ID

125348

CONDITION REPORT

	Engine Compartment Area	COMMENTS
OK	Fan Assembly, Shroud & Radiator	
OK	Hose Condition	
OK	Record Coolant Protection Level	FULL
OK	Oil in Cooling System	
N/A	Coolant DCA Level	
OK	Coolant Level	
OK	Power/Manual Steering Fluid Level	
N/A	Clutch Master Cylinder Fluid Level	
N/A	Brake Fluid Level	
OK	Engine Oil Level	
OK	Oil, Coolant and Other Fluid Leaks	
OK	Belt, Alignment, Condition & Adjustment	
OK	Belt & Engine Driven Components	
OK	Exhaust & Intake Systems	
N/A	Visible Inspection of Starter	
N/A	Other	

	Operational Test	COMMENTS
OK	Batteries - Capable of Starting Engine	
OK	Starter Condition	
OK	Steering Free Play	
N/A	Clutch & Clutch Brake	
OK	Transmission Shifts	
OK	Brakes & Parking Brakes	
OK	Throttle	
N/A	Engine Brake	
OK	Air Pressure Build Up	
OK	Governed Air Pressure (psi)	150
OK	Low Air Warning	
OK	Gauges	
OK	Engine Warning System	
OK	Seat Belts	
OK	HVAC System	
OK	Record A/C Temperature	68
OK	Windshield Wipers & Washers	
OK	Horns	
OK	Door Locks & Latches	
OK	Window Operation	
	Other	

	In Cab Inspection	COMMENTS
OK	Windshield, Door & Any Other Glass	
OK	Interior Condition/ Seats, Panels, Etc.	
OK	DOT Required Safety Equipment	
	Other	

	Outside Inspection	COMMENTS
OK	Paint Condition & Physical Damage	
OK	Mirrors	
OK	Lights and Reflectors	
N/A	Fuel Tank Mounting & Condition	
OK	Batteries & Battery Box	
OK	Intake & Exhaust Mounting & Condition	
	Other	

Under Vehicle Inspection		COMMENTS
N/A	Kingpins/Steering Components	
N/A	Engine/Transmission Mounts	
N/A	Frame, Crossmembers, Fasteners	
N/A	Cab Mounts	
N/A	Driveshafts, U-joints, Yokes	
N/A	Hydraulic Brake Lines & Components	
N/A	Brake Hoses for Chafing & Cracking	
N/A	Air Brake Components	
N/A	Transmission & Differential Fluid Levels	
OK	Transmission & Differential Leaks	
OK	Air Leaks	
N/A	Suspension Condition	
	Other	

Tires/Wheels/Brakes		COMMENTS
X	Tires/Wheels	
N/A	Brakes	NOT VISIBLE

Additional Services	Requested	Status	Comments



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE

09/09/2020

FLEET NAME

UNIT NUMBER

1805

VIN (LAST 8)

J3081105

PO NUMBER

INSPECTOR: 5449

INSPECTION ID

125348

RECONDITIONING AND SUPPLEMENTAL ESTIMATE

ITEM

DESCRIPTION / COMMENTS

Tires/Wheels

| X

COMMENTS:

BACKING PLATES ON BRAKES NOT VISIBLE



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
09/09/2020		1805	J3081105	

INSPECTOR: 5449

INSPECTION ID

125348



VIN



DASH W/ STEERING WHEEL



LEFT SIDE



FRONT LEFT CORNER



FRONT OF BUS



FRONT RIGHT CORNER



RIGHT SIDE



REAR RIGHT CORNER



RIGHT REAR TIRES



REAR OF BUS



REAR LEFT CORNER



LEFT REAR TIRES



ENTRY WAY STEPS AT FRONT DOOR



COMPLETE DRIVERS SEAT



ODOMETER



DASH HOUR METER



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT
 362 - Wells Fargo Equipment Management
 INSP DATE 09/09/2020 FLEET NAME UNIT NUMBER 1805 VIN (LAST 8) J3081105 PO NUMBER

INSPECTOR: 5449
INSPECTION ID
125348



INSIDE OF BUS, FRONT TO BACK



FLOOR OF BUS, FRONT TO BACK



INSIDE OF BUS, BACK TO FRONT




FLOOR OF BUS, BACK TO FRONT



INSIDE RESTROOM #1



INSIDE RESTROOM #2



SEATS




LEFT STEER TIRE



RIGHT STEER TIRE



ENGINE COMPARTMENT



ENGINE FAMILY NUMBER



ENGINE COMPARTMENT
 RIGHT SIDE



ENGINE COMPARTMENT LEFT
 SIDE



INSIDE STORAGE
 COMPARTMENTS



OIL LEAKS



ADDITIONAL 1



DEKRA Services Inc.
Customer Service 770-257-0107

BUS

CLIENT

362 - Wells Fargo Equipment Management

INSP DATE	FLEET NAME	UNIT NUMBER	VIN (LAST 8)	PO NUMBER
09/09/2020		1805	J3081105	

INSPECTOR: 5449

INSPECTION ID

125348



ADDITIONAL 2



ADDITIONAL 3



ADDITIONAL 4



ADDITIONAL 5