



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #5407882 - Patriot 4440 90 ft 4x4 Self Propelled Sprayer



Item Details:

- Features: Hydrostatic, Air Conditioner, Raven Display, Raven Antenna/ Receiver, Tier 4, 2017 US EPA Label, Hydraulic Driven Pump, 1200 L Stainless Steel Tank, Rinse Tank, Single Nozzle Bodies, 380/90R46 380/90R46 Rear Tires, Hydraulic Axle Adjustment
- Meter Reading: 0 Miles
- Serial # : YHT045288
- Inspection Completed: 9/7/21

Shipping Details:

- Location Mississippi (Marshall County)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. You must call at least 24 hours in advance to schedule pickup

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★★☆	Performs within the tolerances expected for age and type of item
★★★☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Serial Number / VIN	YHT045288	
Paint		
Sheet Metal (Fiberglass) Condition		
Glass	No visible damage	

Exterior Lights	Operational	
Steps/Ladders		
Hand Rails		
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Front Corner		
Picture, Right Rear Corner		

General Appearance #1		
General Appearance #2		
General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		

General Appearance #8		
General Appearance #9		
General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		
General Appearance #14		

Control Station		
Item	Assessment	Photo
Control Station #1		
Control Station #2		
Control Station #3		

Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	
Safety #1		

Control Station		
Item	Assessment	Photo
Mirrors		
Seats/Armrests		
Passenger seat	★★★★☆	
Hydraulic Controls	★★★★☆	
Steering Control	★★★★☆	
Drivetrain Controls	★★★★☆	

Oil Pressure	The gauge registers in the operating range. 64 PSI	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter (pre-inspection)	1799.2 hrs	
Hour Meter	1799.8 hrs, Operational hour meter	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	

Engine		
Item	Assessment	Photo
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	

Drivetrain

Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.

Item	Assessment	Photo
Transmission	★★★☆☆ Operational	
Transmission Disconnect	Operational	
Drive/Propel Motors	★★★☆☆	
Limited Function Check	The drivetrain was operational.	
Drivetrain #1		
Drivetrain #2		
Drivetrain #3		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Hydraulic Motors	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Cylinder(s)	★★★★☆	

Cylinder Pins and Bushings	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Hydraulics #7		 A close-up photograph of a hydraulic cylinder, labeled #7, showing its silver-colored rod and black seal. The cylinder is mounted on a red metal frame. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Hydraulics #8		 A close-up photograph of a hydraulic cylinder, labeled #8, showing its red body and mounting bracket. The cylinder is part of a larger red hydraulic system. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Hydraulics #9		 A close-up photograph of a hydraulic cylinder, labeled #9, showing its red body and mounting bracket. The cylinder is part of a larger red hydraulic system. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Hydraulics #10		 A close-up photograph of a hydraulic cylinder, labeled #10, showing its red body and mounting bracket. The cylinder is part of a larger red hydraulic system. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Hydraulics #11		 A close-up photograph of a hydraulic cylinder, labeled #11, showing its red body and mounting bracket. The cylinder is part of a larger red hydraulic system. An "IRON PLANET" logo is visible in the bottom right corner of the image.
Hydraulics #12		 A close-up photograph of a hydraulic cylinder, labeled #12, showing its red body and mounting bracket. The cylinder is part of a larger red hydraulic system. An "IRON PLANET" logo is visible in the bottom right corner of the image.

Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Booms and Boom Tree	★★★★☆	
Tank	★★★★☆	
Tank Saddle	★★★★☆	
Plumbing	★★★★☆	
Electrical	★★★★☆	
Foam Marker	★★★★☆	

Fluid Flush System	★★★★☆	
Controller	★★★★☆ Appears complete	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		

Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		

Chassis #13		
Chassis #14		
Chassis #15		
Chassis #16		
Chassis #17		
Chassis #18		
Chassis #19		

Chassis #20		
Chassis #21		
Chassis #22		
Chassis #23		
Chassis #24		
Steering Linkage	★★★★☆	
Brake Type	Hydraulic	
Master Cylinder	★★★★☆	

Brake Control	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Left Front Tire		
Left Rear Tire		
Right Rear Tire		
Right Front Tire		

Tread Depth	LF 16/32", LR 34/32", RR 24/32", RF 30/32"	
Wheel Condition	★★★★☆	
Wheel Studs, Nuts, Lugs	★★★★☆	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		

Chassis #6		
Chassis #7		
Chassis #8		
Chassis #9		
Chassis #10		
Chassis #11		
Chassis #12		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved