



# Aspen Field Services

Job #: 27081 /

Serial #: 502515067

For more information, visit:

[wellsfargo.com/equipseller](https://wellsfargo.com/equipseller)

2015 NVX5025 SHUTTLE WAGON RAILCAR



Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/sYaJbdRtvthp8MwJc/full\\_report\\_0027081\\_sYaJbdRtvthp8MwJc.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/sYaJbdRtvthp8MwJc/full_report_0027081_sYaJbdRtvthp8MwJc.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2015
Make	Shuttlewagon
Model	NVX5025
Serial Number	502515067
Type	Railcar
Inspection Date	1/8/2021
Location of Business	JJ Kane Auctioneers - 2157 NE Jacksonville Rd , Ocala, FL, 34470
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Driver Seat	Tear
Passenger Seat	Good Condition
Controls	Standard
Keyless Start	None
Foot Pedals	Good Condition
Hours	3845



# Aspen Field Services

Job #: 27081 /

Serial #: 502515067

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

2015 NVX5025 SHUTTLE WAGON RAILCAR

Inspection Details Cont'd	
Cab A-C	Yes
Cab Heat	Yes
Cab A/C Condition	Good Condition
Cab Heat Condition	Good Condition
Backup Camera	Yes
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Bridgestone: Not Available
Front Right Tire Size	Not Visible
Front Right Tire Condition	Gouge
Front Right Tire Depth Measurement	NA
Front Left Tire Part Number	Michelin: Not Available
Front Left Tire Size	Not Visible
Front Left Tire Condition	Gouge
Front Left Tire Depth Measurement	NA
Back Right Tire Part Number	Bridgestone: Not Available
Back Right Tire Size	14.00R24
Back Right Tire Condition	Gouge
Back Right Tire Depth Measurement	NA
Back Left Tire Part Number	Bridgestone: Not Available
Back Left Tire Size	14.00R24
Back Left Tire Condition	Gouge
Back Left Tire Depth Measurement	NA
Mismatched Tires	Yes
Front Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Back Left Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Front Wheel Hydraulics	Good Condition
Rear Wheel Hydraulics	Good Condition
Tailgate Lights	Good Condition
Working Lights	Good Condition
Driver Side Door	Good Condition
Passenger Door	God Condition
Side Glass Complete	Yes
Muffler	Good Condition
Intake Screen	Good Condition
Engine Door	Good Condition

Inspection Details Cont'd	
Engine Compartment	Dirty
Engine MFR	Cummins
Engine Serial Number	73803048
Customer Decals Visible on Unit	No
Railings	Good Condition
Steps	Good Condition
Comments	All four tires are worn out and need to be replaced.